Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
31584
Org. Est. # 046767

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 04/27/2022**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 153364

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
RTV - Valve cover gasket sealer *000 043 305 46*	1.00	28.87	28.87
Spark plug tube seal - inner *996 104 203 00*	3.00	9.92	29.76
Spark plug tube seal - Outer *999 701 761 41*	3.00	2.72	8.16
CAMSHAFT ADJUSTER SEAL *966 105 244 03*	2.00	11.87	23.74
OIL PUMP SEAL *999 707 554 40*	1.00	5.65	5.65
Exhaust gasket *996 111 113 50*	2.00	5.58	11.16
EXHAUST MANIFOLD GASKET *996 111 107 55*	2.00	13.43	26.86
DISC ROTOR - Front, Left *996 351 405 01*	1.00	241.75	241.75
DISC ROTOR - Front, Right *996 351 406 01*	1.00	241.75	241.75
Brake pad set - Front *996 351 949 12*	1.00	332.69	332.69
Brake pad sensor - Front *996 612 365 01*	2.00	29.76	59.52
Brake hardware kit - Front *996 351 959 11*	1.00	63.09	63.09
BRAKE PAD SHIM - SET, FRONT *996 351 089 01*	1.00	43.88	43.88
DISC ROTOR - Rear,Right *996 352 406 02*	1.00	228.50	228.50
DISC ROTOR - Rear,Left *996 352 405 02*	1.00	228.50	228.50
Brake pad set - Rear *996 352 949 03*	1.00	201.28	201.28
Brake pad sensor - Rear *996 612 365 01*	2.00	29.76	59.52
Brake hardware kit- Rear *996 351 959 01*	1.00	37.22	37.22
BRAKE PAD SHIM- SET, REAR *996 351 088 02*	1.00	46.44	46.44
STABILIZER LINK FRONT *996 343 073 05*	2.00	77.87	155.74
STABILIZER LINK REAR *996 333 069 04*	2.00	56.60	113.20

Labor Description	Ext
Customer states that check engine indicator is illuminated and vehicle engine idle is too high. Performed smoke test to detect vacuum leaks. Found excessive vacuum leaks on drive's side valve cover gasket and spark plug tube seals.	n/c
Performed smoke test to detect vacuum leaks. Found excessive vacuum leaks on drivers side valve cover gasket and spark plug tube seals. Also performed ECU diagnostics, found fault code P0507 related to vacuum leak and idle speed. Initially valve cover & tube seals should be replaced, to seal up vacuum leaks & oil leaks from valve cover. Further diagnostic will be required for check engine light.	
VALVE COVER GASKET - Remove & Replace - Driver's side	680.00
Replaced Spark Plug Tube Seals - inner & outer, Camshaft adjuster seals and Oil pump seal. Replaced exhaust manifold gaskets and exhaust connecting gaskets.	
Front brakes are below 40% life left.	240.00
Remove & Replace both sides front - disc rotor, brake pads and brake pad wear sensors. Inspect and lubricated brake calipers.	
Rear brakes are below 20% life left.	330.00
Remove & Replace both sides rear - disc rotor, brake pads and brake pad wear sensors. Inspect and lubricated brake calipers.	
STABILIZER LINK - Remove & Replace - Both FRONT	60.00
STABILIZER LINK - Remove & Replace - Both Sides REAR	75.00
TIE ROD &/OR END - Remove & Replace - Outer BOTH SIDES	150.00
CONTROL ARM - Remove & Replace - Lower,Both	250.00
WATER PUMP DRIVE BELT - Remove & Replace - Normally Aspirated - [Includes: Serpentine type Belt(s).]	75.00
FOUR WHEEL ALIGNMENT	360.00
Found one of the molded cooling hoses (t-connectors cracked). Remove & replace cooling hose.	240.00
CUSTOMER REQUESTED TO REPAIR/RECONDITION ALL 4 WHEEL WITH FACTORY REFINISH.	800.00
RECONDITIONED ALL 4 WHEELS WITH FACTORY COLOR CODE 7202, INCLUDING CENTER CAPS. MOUNT TIRES AND BALANCE. REPLACED RUBBER TPMS VALVE STEM SEALS ON ALL WHEELS.	
AFTER ALL REPAIRS ROAD TESTED VEHICLE TO CONFIRM ALL REPAIRS. AFTER ROAD TEST FOUND VISIBLE INTAKE VACUUM HOSE LEAKING FROM CONNECTOR.	280.00
PERFORMED SMOKE TEST TO VERIFY FOR ANY ADDITIONAL VACUUM LEAKS. FOUND INTAKE HOSE SEAL EXCESSIVE VACUUM LEAK. REPAIRED INTAKE HOSE SEAL TO ELIMINATE THE LEAK. PERFORMED SMOKE TEST AFTER REPAIR. NO LEAKS FOUND. ROAD TESTED AGAIN. NO FAULTS FOUND.	

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
31584
Org. Est. # 046767

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 04/27/2022**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 153364

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
TIE ROD &/OR END - Outer, Front *996 347 131 04*	2.00	109.04	218.08
CONTROL ARM - Front, Rearword *996 341 053 19*	2.00	389.82	779.64
ALTERNATOR DRIVE BELT - w/A/C *996 102 151 66*	1.00	58.79	58.79
Cooling hose Molded *996 106 850 06*	1.00	77.44	77.44
COOLANT (1 gallon) *000 043 301 49*	1.00	18.87	18.87
TMPS VALVE STEM *100*	4.00	3.00	12.00
INTAKE HOSE O-RING (85mm) *101*	1.00	3.50	3.50
Shop Supplies			82.75

Labor Description	Ext
Hazardous Materials	96.54

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	343.84

Org. Estimate 6,092.81 Revisions 0.00 Current Estimate 6,092.81

Labor:	**3,540.00**
Parts:	**3,438.35**
HazMat:	**96.54**
SubTotal:	**7,074.89**
Tax:	**343.84**
Total:	**7,418.73**
Bal Due:	**$0.00**

[Payments - American Express - $7,418.73]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 4/14/2022 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32025
Org. Est. # 047280

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 10/13/2022**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 153761

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
MOTUL 100% SYNTHETIC ENGINE OIL. PORSCHE SPEC # A40 *SAE 5W-40*	9.50	13.49	128.16
ENGINE OIL FILTER KIT *996 107 225 53*	1.00	24.94	24.94
ENGINE MOTOR MOUNT - PARTS SUPPLIED BY CUSTOMER *1*	2.00	0.00	n/c
Shop Supplies			4.36

Labor Description	Ext
CUSTOMER REQUESTED ENGINE OIL CHANGE. PERFORMED ENGINE OIL & FILTER CHANGE. RESET ELECTRONIC SERVICE REMINDER. ADJUSTED TIRE PRESSURE. INSPECT & TOP OFF ALL FLUIDS.	30.00
CUSTOMER REQUESTED TO REPLACED ENGINE MOTOR MOUNTS. REMOVE & REPLACE BOTH ENGINE MOTOR MOUNTS.	180.00

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	15.75

Org. Estimate 383.21 Revisions 0.00 Current Estimate 383.21

Labor:	**210.00**
Parts:	**157.46**
SubTotal:	**367.46**
Tax:	**15.75**
Total:	**383.21**
Bal Due:	**$0.00**

[Payments - Visa - $383.21]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 10/13/2022 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32042
Org. Est. # 047288

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 10/21/2022**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 153822

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
CV BOOT - KIT, FRONT- OUTER *996 349 291 00*	1.00	64.64	64.64
CV BOOT - KIT, FRONT - INNER *996 349 293 00*	1.00	64.64	64.64
CV Boot Clamp-Front Inner *997 349 957 00*	1.00	3.24	3.24
CV Boot Clamp-Front Outer *996 349 257 00*	1.00	8.38	8.38
TRANSMISSION MOUNT - MANUAL *996 375 055 05*	1.00	79.11	79.11
BUMPER STOP - TRANS MOUNT *996 375 255 05*	2.00	9.61	19.22

Labor Description	Ext
LEFT FRONT OUTER AXLE BOOT IS TORN. REPLACEMENT IS REQUIRED. REMOVE LEFT FRONT AXLE ASSEMBLY. REPLACE AXLE BOOT & CLAMPS WITH NEW GREASE. REINSTALL AXLE ASSEMBLY.	300.00
REMOVE & REPLACE TRANSMISSION (6-SPEED MANUAL) TRANSMISSION MOUNT.	150.00

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	23.92

Org. Estimate 661.59 Revisions 0.00 Current Estimate 661.59

Labor:	**450.00**
Parts:	**239.23**
SubTotal:	**689.23**
Tax:	**23.92**
Total:	**713.15**
Bal Due:	**$0.00**

[Payments - Visa - $713.15]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 10/21/2022 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32307
Org. Est. # 047621

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 02/17/2023**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 154284

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
DOOR WINDOW REGULATOR - Coupe, Right *996 542 076 04*	1.00	324.99	324.99
DOOR WINDOW REGULATOR - Coupe, Left *996 542 075 05*	1.00	324.99	324.99
SEAT BELT ADJUSTER COVER - IF NEEDED *997 803 521 00 A03*	1.00	104.14	104.14
Shop Supplies			17.69

Labor Description	Ext
REMOVE & REPLACE DRIVER'S & PASSENGER SIDE WINDOW REGULATORS.	600.00
DURING REPLACEMENT OF BOTH WINDOW REGULATORS, FOUND WINDOW REGULATOR MOTOR BUSHINGS WORN. PERFORMED REPAIR OF BOTH LEFT & RIGHT WINDOW REGULATOR MOTORS. ***ADVISED CUSTOMER THAT DRIVER'S SIDE DOOR LATCH NEEDS REPLACEMENT FOR PROPER WINDOW SLIDE OPERATION***	120.00
INSTALL SEAT BELT MOUNT COVER - B PILLAR.	n/c

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	77.18

Org. Estimate 1,568.99 Revisions 0.00 Current Estimate 1,568.99

Labor:	**720.00**
Parts:	**771.81**
SubTotal:	**1,491.81**
Tax:	**77.18**
Total:	**1,568.99**
Bal Due:	**$0.00**

[Payments - MasterCard - $1,568.99]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 2/17/2023 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32355
Org. Est. # 047668

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 03/08/2023**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 154356

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
DOOR LOCK ACTUATOR ASSEMBLY *9A7 837 015 03*	1.00	371.45	371.45
BATTERY *94R/PG*	1.00	207.27	207.27

Labor Description	Ext
REPLACED DRIVER'S SIDE DOOR LOCK ASSEMBLY. REMOVED WINDOW ACTUATOR STOPPERS. INSTALLED NEW BATTERY.	200.00
CUSTOMER REQUESTED AND WE PERFORMED FOLLOWING REPAIRS/INSTALLS: 1. Install interior led bulbs. 2. Replace all new headlight bulbs. 3. Vanity mirror cover install. 4. Side markers install. 5. Headlight washer(s) install. 6. Wire install battery tender cord. 7. Repaired sunroof switch. ADVISED CUSTOMER THAT SUNROOF SWITCH AND UPPER COWL MAY NEED REPLACEMENT IF REPAIR DOESN'T HOLD.	400.00
SUNROOF INNER COVER IS LOOSE. MORE TIME IS NEEDED TO DIAGNOSE SUNROOF INNER COVER AND SUNROOF TRACK. AIR BAG LIGHT IS ON DUE TO FAULTY PASSENGER SIDE SEAT BELT BUCKLE.	n/c

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	57.87

Org. Estimate 960.49 Revisions 0.00 Current Estimate 960.49

Labor:	**600.00**
Parts:	**578.72**
SubTotal:	**1,178.72**
Tax:	**57.87**
Total:	**1,236.59**
Bal Due:	**$0.00**

[Payments - Visa - $1,236.59]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 3/8/2023 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32840
Org. Est. # 048243

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 10/27/2023**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 155202

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
NUMERIC - MANUAL SHIFTER - KIT (PARTS SUPPLIED BY CUSTOMER Size: 0 *AFTRMKT*	1.00	0.00	n/c
HAND BRAKE BOLT *996 424 569 01*	1.00	14.89	14.89
MOTUL 100% SYNTHETIC ENGINE OIL. PORSCHE SPEC # A40 *SAE 5W-40*	9.50	13.49	128.16
ENGINE OIL FILTER KIT *996 107 225 53*	1.00	24.94	24.94
MANUAL GEAR BOX FLUID - MOTUL 105777 *SAE 75W90*	5.00	34.37	171.85
DIFFERENTIAL FLUID - MOTUL 105777 *SAE 75W90*	2.00	34.37	68.74
HEATER SEAT ELEMENT *996 653 105 01*	2.00	191.20	382.40
DRIVERS SEAT SIDE JOINT COVER (BLACK) *996 521 315 02 5Q0*	1.00	167.76	167.76
SEAT REPAIR SUPPLIES (drivers seat) *7112*	1.00	25.00	25.00
SUNROOF TRACK ASSEMBLY (USED - UPDATED UNIT) PART SUPPLIED BY CUSTOMER *951 856 914 000*	1.00	0.00	n/c
SUN ROOF MOTOR (USED - UPDATED UNIT) PART SUPPLIED BY CUSTOMER *997 624 211 00*	1.00	0.00	n/c
ENGINE AIR FILTER *996 110 131 52*	1.00	50.10	50.10
WASHER NOZZLE *997 628 077 00*	1.00	35.50	35.50
STRUT ASSEMBLY - AWD Front (PARTS SUPPLIED BY CUSTOMER) *996 343 043 44*	2.00	0.00	n/c
STRUT MOUNT - LEFT, FRONT *996 343 015 04*	1.00	316.80	316.80
STRUT MOUNT - RIGHT, FRONT *996 343 016 04*	1.00	316.80	316.80
Strut Bump Stop, FRONT *996 343 301 02*	2.00	27.00	54.00

Labor Description	Ext
CUSTOMER REQUESTED TO INSTALL NUMERIC SHIFTER FOR MANUAL TRANSMISSION. REMOVE CENTER COWL. DISCONNECT MANUAL SHIFTER AND DISCONNECT SHIFTER CABLES. REMOVE FACTORY SHIFTER ASSEMBLY. INSTALL NEW NUMERIC MANUAL SHIFTER ASSEMBLY. CONNECT AND ADJUST MANUAL SHIFTER CABLES. RE-INSTALL INNER COWL.	800.00
REMOVE PARKING BRAKE LEVER. REPLACE LEVER PIVOT PIN AND REINSTALL. ADJUST PARKING BRAKE CABLE FOR PROPER E-BRAKE OPERATION & E-BRAKE HANDLE TENSION.	250.00
CUSTOMER REQUESTED ENGINE OIL CHANGE. PERFORMED ENGINE OIL & FILTER CHANGE. RESET ELECTRONIC SERVICE REMINDER. ADJUSTED TIRE PRESSURE. INSPECT & TOP OFF ALL FLUIDS.	30.00
MANUAL TRANSMISSION FLUID - Drain & Refill	65.00
DIFFERENTIAL FLUID - Drain & Refill - Front	65.00
REMOVE CENTER CONSOLE CUP HOLDER. CUP HOLDER IS NOT REPAIRABLE. CUSTOMER REQUESTED TO PERMANENTLY SECURE CUP HOLDER MAKING IT INOPERABLE.	100.00
DIS-CONNECTED ELECTRICAL HARNESSES. REMOVED BOTH FRONT SEATS. DIS-ASSEMBLED BOTH SEATS. REPLACED HEATING ELEMENT IN PASS. SEAT. DRIVER'S SEAT INNER FOAM IS TORN IN MULTIPLE AREAS, PLASTIC SUPPORTS AND ELECTRICAL SUPPORTS ARE CRACKED/BROKEN. REPAIRED/REBUILT INNER SEAT PORTIONS OF THE FOAM. INSTALLED NEW HEATING ELEMENT. HOT GLUED ALL BROKEN PLASTIC SUPPORTS & BRACKETS. RE-CONNECTED ELECTRICAL WIRING HARNESSES AND RE-INSTALLED BOTH FRONT SEATS. INSTALLED DRIVER'S SIDE JOINT SEAT COVER.	850.00
REMOVE ALL INTERIOR PILLAR PANELS AND HEADLINER. DISCONNECT ALL ELECTRICAL ITEMS. REMOVE SUNROOF TRACK ASSEMBLY. TRANSFER EXTERIOR SUNROOF COVER TO NEW TRACK ASSEMBLY. INSTALL SUNROOF TRACK ADJUST TRACK FRAME FOR PROPER ROOF OPERATION. RE-INSTALL ALL INTERIOR PILLAR PANELS AND HEADLINER. RE-CONNECT ALL ELECTRICAL ITEMS. PERFORM SUNROOF MOTOR SYNCHRONIZATION PROCEDURE.	1,200.00
AIR CLEANER ELEMENT - Remove & Replace - Normally Aspirated	70.00
REPAIR GLOVE BOX	150.00
REPLACE DRIVER'S SIDE WINDSHIELD WASHER NOZZLE	50.00
REMOVE FRONT & REAR SUSPENSION STRUTS. ASSEMBLE NEW STRUTS WITH NEW STRUT MOUNTS, H&R LOWERING COIL SPRINGS.	1,400.00

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32840
Org. Est. # 048243

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 10/27/2023**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 155202

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
STRUT ASSEMBLY - AWD REAR (PARTS SUPPLIED BY CUSTOMER) *24-029933*	2.00	0.00	n/c
STRUT MOUNT - REAR *996 333 059 03*	2.00	163.31	326.62
Shock Bump Stop, REAR *996 333 105 03*	2.00	40.00	80.00
Shock Bellows, REAR *993 333 107 01*	2.00	30.00	60.00
H&R Sport Spring Set - Front & Rear fitment Avg Low 1.0"F & 1.0"R. *29486*	1.00	270.00	270.00
Suspension Ride Height Sensor Bracket *9996 341 371 03*	1.00	4.50	4.50
CONTROL ARM - FRONT, FORWARD (WARRANTY) *996 341 053 19*	2.00	0.00	n/c
STABILIZER LINK FRONT *996 343 073 05*	2.00	77.87	155.74
STABILIZER LINK REAR *996 333 069 04*	2.00	56.60	113.20
BATTERY - (WARRANTY) *94R/PG*	1.00	0.00	n/c
STARTER CABLE *996 607 019 03*	1.00	100.17	100.17
LUG BOLT *997 361 203 02*	4.00	14.70	58.80

Labor Description	Ext
INSTALL NEW FRONT & REAR STABILIZER LINKS (WARRANTY WORK). REPLACED BOTH FRONT FORWARD CONTROL ARMS (WARRANTY WORK). Replace Suspension Ride Height Sensor Bracket.	
STABILIZER LINK - Remove & Replace - Both FRONT (WARRANTY)	n/c
STABILIZER LINK - Remove & Replace - Both Sides REAR (WARRANTY)	n/c
FOUR WHEEL ALIGNMENT	360.00
BATTERY REMOVE & REPLACE (WARRANTY)	n/c
REMOVE & REPLACE STARTER CABLE.	360.00
CUSTOMER REQUESTED TO PERFORM CLIMATE CONTROL BLEND DOOR SERVICE. PERFORMED CLIMATE CONTROL INNER FILTER SERVICE. VACUUM & CLEAN OLD FOAM FROM CLIMATE CONTROL. INSTALLED NEW FOAM TO FILTER.	200.00
PERFORMED "FRUNK" ADJUSTMENT. INSTALL WINTER WHEEL/TIRE SET. WINTER TIRE TREAD IS AT: -RR = 7mm (8/32) -LR = 7mm (8/32) -RF = 8mm (9/32) -LF = 8mm (9/32)	n/c
PERFORMED MULTIPLE ROAD TESTS TO CONFIRM PROPER OPERATION OF ALL SYSTEMS FOR ABOVE REPAIRS & SERVICES.	n/c
PERFORMED DETAIL OF THE VEHICLE. EXTERIOR VEHICLE WASH, BUFF AND POLISH. CLEAN WHEELS & DRESS TIRES. INTERIOR VACUUM, LEATHER SEAT CONDITIONER, CLEAN ALL WINDOWS AND INTERIOR.	380.00
COMPLEMENTARY DETAIL OF THE VEHICLE.	-380.00
ASKED CUSTOMER IF HE WOULD LIKE TO KEEP ALL PARTS REMOVED FROM HIS VEHICLE. CUSTOMER REQUESTED DISPOSAL OF ALL OEM PARTS REMOVED FROM VEHICLE.	n/c

X_____ DATE: 11/22/23 TIME: 14:30

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	292.60

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
32840
Org. Est. # 048243

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 10/27/2023**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 155202

VIN # : WP0AA2994 **3S622267**

Part Description	/ *Number*	Qty	Sale	Ext	Labor Description	Ext

Org. Estimate 102.72 Revisions 0.00 Current Estimate 102.72

Labor:	**5,950.00**
Parts:	**2,925.97**
SubTotal:	**8,875.97**
Tax:	**292.60**
Total:	**9,168.57**
Bal Due:	**$0.00**

[Payments - American Express - $9,168.57]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 10/21/2023 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
33441
Org. Est. # 048973

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 11/04/2024**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 156409

VIN # : WP0AA2994 **3S622267**

Part Description / *Number*	Qty	Sale	Ext
MOTUL 100% SYNTHETIC ENGINE OIL. PORSCHE SPEC # A40 *SAE 5W-40*	9.50	14.50	137.75
ENGINE OIL FILTER KIT *996 107 225 53*	1.00	24.94	24.94
TIE ROD END - OUTER, FRONT *996 347 131 05*	2.00	109.04	218.08
AXLE ASSEMBLY - FRONT, LEFT (PART SUPPLIED BY CUSTOMER) *996 349 038 11*	1.00	0.00	n/c
EXHAUST CLAMP *1010*	1.00	7.00	7.00
Shop Supplies			17.25

Labor Description	Ext
CUSTOMER REQUESTED ENGINE OIL CHANGE. PERFORMED ENGINE OIL & FILTER CHANGE. RESET ELECTRONIC SERVICE REMINDER. ADJUSTED TIRE PRESSURE. INSPECT & TOP OFF ALL FLUIDS.	30.00
CUSTOMER STATES THAT PASSENGER FRONT SEAT IS NOT WORKING. PERFORMED SEAT AND ELECTRICAL INSPECTION. FOUND BURNED 30AMP FUSE. FURTHER INSPECTION FOUND BROKEN WIRES IN THE BACK REST SEAT PORTION. REMOVE PASS. FRONT SEAT. REMOVE WIRING HARNESS. PERFORMED ELECTRICAL REPAIR OF BROKEN/TORN WIRES. REPLACED 30AMP FUSE. TESTED ELECTRICAL COMPONENTS AFTER HARNESS REPAIR. REINSTALLED WIRING HARNESS AND SEAT. PASS. FRONT SEAT IS WORKING PROPERLY.	260.00
CUSTOMER COMPLAINTS OF FRONT SUSPENSION/STEERING NOISE WHILE DRIVING AT LOW SPEED. PERFORMED FRONT SUSPENSION & STEERING INSPECTION. FOUND LEFT FRONT OUTER TIE ROD FAULTY. REMOVE & REPLACE BOTH FRONT OUTER TIE ROD ENDS.	150.00
REMOVE & REPLACE BOTH FRONT OUTER TIE ROD ENDS. WARRANTY WORK. LABOR CREDIT.	-150.00
DURING INSPECTION FOUND RIGHT FRONT AXLE ASSEMBLY FAULTY. REMOVE & REPLACE RIGHT FRONT AXLE ASSEMBLY.	340.00
FOUR WHEEL ALIGNMENT	360.00
CUSTOMER STATES THAT THERE IS A RATTLE FROM EXHAUST AROUND 2K RPM. PERFORMED EXHAUST INSPECTION. FOUND PASS. SIDE EXHAUST TIP CLAMP MISSING. INSTALLED NEW PASS. SIDE EXHAUST TIP CLAMP.	n/c
CUSTOMER REQUESTED TO REPLACE CENTER CONSOLE CUP HOLDER ASSEMBLY. REMOVE CENTER CONSOLE CLIMATE CONTROL VENTS TO ACCESS CUP HOLDER ASSEMBLY. REPLACE CUP HOLDER AND REINSTALL VENTS & CENTER CONSOLE.	60.00
PERFORMED EXTERIOR HAND WASH OF THE VEHICLE.	n/c

[Recommendations]
Perform Lube, Oil & Filter Exchange on 4/12/2025 or 161400 Miles.

Taxes	
TAX RATES	40.50

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Infinity Auto Haus
353 W COLFAX
Palatine, IL. 60067
Phone: 847-496-4577 Fax: 847-496-7648

INVOICE
33441
Org. Est. # 048973

Invoice from History

Printed Date: 09/20/2025 **Work Completed: 11/04/2024**

2003 Porsche - 911 Carrera 4S - 3.6L, H6 (220CI) VIN(A)
Lic # : DK38363 Odometer In : 156409

VIN # : WP0AA2994 **3S622267**

Part Description	/ *Number*	Qty	Sale	Ext	Labor Description	Ext

Org. Estimate 214.20 Revisions 0.00 Current Estimate 214.20

Labor:	**1,050.00**
Parts:	**405.02**
SubTotal:	**1,455.02**
Tax:	**40.50**
Total:	**1,495.52**
Bal Due:	**$0.00**

[Payments - Visa - $1,495.52]

YOUR COMPLETE SATISFACTION IS OUR GOAL

Vehicle Received: 11/1/2024 Customer Number : 4468

PLEASE CALL JIM @ 847-496-4577 WITH ANY QUESTIONS, PROBLEMS, OR COMPLIMENTS THANK YOU

IF YOU ARE NOT COMPLETELY SATISFIED WITH ALL OF OUR SERVICES, PLEASE LET US KNOW IMMEDIATELY

6 MONTHS OR 6000 MILE WARRANTY

WARRANTIES WILL BE VOID IF THERE IS EVIDENCE OF MISUSE OF THE VEHICLE.

ELECTRICAL WARRANTIES ARE VOIDED IF WATER OR OTHER TYPES OF FLUIDS OCCURED.

Signature _____ Date_____

Visit us on the web: www.WWW.INFINITYAUTOHAUS.COM Email Address:*infinityautohaus@gmail.com*

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Shook ENTERPRISES

WWW.SHOOKENTERPRISES.COM

106 N. CHAPARRAL
CORPUS CHRISTI, TEXAS 78401
PHONE (361) 881-9061 | FAX (361) 884-9061

[redacted]	DATE IN: 8/31/1971	DATE PROMISED: 11/22/2021	
	MECHANIC: JP	ORDER WRITTEN BY: SS	
	BUSINESS PHONE: -	EXT: -	CELL PHONE: [redacted]
ADDRESS: -	HOME PHONE: -		E-MAIL ADDRESS: -
CITY: - STATE: - ZIP: -	CALL WITH ESTIMATE: YES / NO		MILEAGE: 152,994
YEAR, MAKE AND MODEL: 2003 PORSCHE CARRERA 4S	VIN: WP0AA29943S622267	LICENSE NO.: NZB 0761	STATE: TX

SERVICES REQUESTED / DESCRIPTION OF WORK	
	$ -
REMOVE TRANSAXLE ASSEMBLY AND INSPECT CLUTCH	$ -
--REMOVE FLYWHEEL FOR RESURFACING	$ -
--REPLACE CRANKSHAFT REAR MAIN SEAL	$ -
--INSTALL NEW IMS BEARING KIT AND DIRECT OIL FLOW KIT	$ -
--REINSTALL FLYWHEEL AND NEW CLUTCH ASSEMBLY	$ -
--RE-INSTALL TRANSAXLE	$ -
--REPLACE SEPARATED FRONT DRIVE SHAFT FLEX JOINT	$ -
--START ENGINE AND TEST DRIVE	$ -
REPLACE WORN SPARK PLUGS	$ -
DRAIN OLD FUEL FROM TANK AND REPLENISH	$ -
REPLACE WORN / NOISY SERPENTINE FAN BELT	$ -
PERFORM ENGINE OIL AND FILTER AND LUBRICATION SERVICE	$ -
AFTER DRIVIN VEHICLE FOR SOME TIME THE CHECK ENGINE	$ -
LAMP CAME ON AND VEHICLE BEGAN TO RUN ROUGH	$ -
--RUN DIAGNOSTIC CODES---ALL OF THE ETRIEVED CODES	$ -
PERTAINED TO A THROTTLE BODY ISSUE	$ -
--REPLACE THE THROTTLE BODY ASSEMBLY , CLEAR DIAGNOSTIC	$ -
CODES & TEST DRIVE VEHICLE---VEHICLE DRIVES AND STARTS	$ -
NOTICEABLY BETTER AND NO CODES WERE RESET	$ 4,435.00
	$ -
TOTAL LABOR	$ 4,435.00

QTY.	PART NO. AND DESCRIPTION (All parts new unless otherwise specified)	UNIT COST	AMOUNT
1	CLUTCH ASSEMBLY	$ 680.00	$ 680.00
1	REAR MAIN SEAL	$ 32.88	$ 32.88
1	IMS BEARING KIT	$ 135.00	$ 135.00
1	DOF KIT	$ 899.00	$ 899.00
1	DRIVE SHAFT FLEX JOINT---FRONT DRIVESHAFT	$ 94.43	$ 94.43
6	SPARK PLUGS	$ 13.44	$ 80.64
1	OIL FILTER	$ 17.87	$ 17.87
11	QTS.OIL---SYNTHETIC	$ 9.99	$ 109.89
1	OIL DRAIN PLUG AND SEAL RING	$ 9.49	$ 9.49
2	SWEPCO 503	$ 14.95	$ 29.90
1	O'RING SEAL	$ 5.99	$ 5.99
2	LBS. REFRIGERANT	$ 19.95	$ 39.90
4	OZ. REFRIGERANT OIL	$ 3.49	$ 13.96
2	FUEL DRIER	$ 4.49	$ 8.98
1	THROTTLE BODY SSEMBLY	$ 272.43	$ 272.43
2	QTS. OIL---SYNTHETIC	$ 9.99	$ 19.98
1	SERPENTINE FAN BELT	$ 48.79	$ 48.79
	**********SUBLET : FLYWHEEL RESURFACING**********		$ -

DATE	PAYMENT LEDGER	C/C	CH	CA
3/14/22	PAID # 754487354		X	

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that you will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. Vehicles will be accessed a daily storage fee of $15.00 and will begin on the 11th day following notification.

SIGNATURE

SAVE OLD PARTS: YES / NO

TOTAL PARTS	$ 2,499.13
TOTAL LABOR	$ 4,435.00
TOTAL SUBLET	$ 325.00
GAS, OIL AND GREASE	$ 30.00
SHOP SUPPLIES	$ 18.30
EPA / WASTE DISPOSAL	$ 6.00
FREIGHT	$ 12.30
[MISC]	$ -
[MISC]	$ -
[MISC]	$ -
TAX	$ 206.18
GRAND TOTAL	$ 7,531.91

MBL WEST COMMUNICATION
2111 NE M L KING BLVD
PORTLAND, OR 972123725

12/13/2018 09:24:20

CREDIT CARD

AMEX SALE

Card #	XXXXXXXXXXX5000
SEQ #:	1
Batch #:	39
INVOICE	1
Approval Code:	502880
Entry Method:	Swiped
Mode:	Online

SALE AMOUNT $899.90

CUSTOMER COPY

T CAR AUDIO

Jr Blvd
7212

Invoice

Date	Invoice #
12/12/2018	138301

Ship To

Rep	Ship	Via	F.O.B.	Project
PETER	12/12/2018		911, 2003	

Quantity	Item Code	Description	Price Each	Amount
		front speakers		
1	CCWR254	2.5" wide-band driver. midrange/tweeter	219.95	219.95
1	TEMPO ULTRA 5 ...	TEMPO ULTRA 5 WOOFER	299.95	299.95
3.5	Installation - Standa...	Standard Installation Services	100.00	350.00
30	PARTS	Miscellaneous Installation Parts.	1.00	30.00
		SUB-TOTAL		899.90
		step 2, CarPlay/Android Auto		
		SUB-TOTAL		899.90
		step 3, Subwoofer		
		SUB-TOTAL		899.90

Total $899.90

Porsche Austin
200 E Hunland Dr
AUSTIN, TX 78752
512-371-1155
39300982131921

SALE

21 Store: 0001 Term: 0002
REF#: 00000011
: 034 ARN: 004819004944
13:24:30
: 580048698783868
ODE: 0317BD
Chip
*4591

NT $3,593.25

APPROVED

PORSCHE

Porsche Austin

200 E. Hunland Dr. • Austin, TX 78752 • (512)371-1155 • 800-687-1747

PARTS HAS UNIQUE ACCESSORIES
FOR UNIQUE CARS
SEE OUR PARTS DEPARTMENT FOR DETAILS

[redacted]

ADVISOR: SHEALEA GREER 800445	TAG NO.: 4895	INVOICE DATE: 02/17/20	POCS82150
LABOR RATE: 205.00	LICENSE NO.	MILEAGE: 150,140 /	COLOR / STOCK NO.
YEAR / MAKE / MODEL: 03/PORSCHE/911/		DELIVERY DATE	DELIVERY MILES
VEHICLE I.D. NO.: WP0AA29943S622267		SELLING DEALER NO.	PRODUCTION DATE
F.T.E. NO.	P.O. NO.	R.O. DATE: 01/29/20	
BUSINESS PHONE	COMMENTS		MO: 150178

TOTALS----------

SHOP SUPPLY CHARGES ARE FOR PARTS AND CHEMICALS USED WHILE SERVICING YOUR VEHICLE THAT DO NOT HAVE A SPECIFIC PART NUMBER. THESE MAY INCLUDE, BUT ARE NOT LIMITED TO: BRAKE, ELECTRICAL, AND CARBURATOR CLEANING SOLVENTS, SILICONE, TEFLON, AND MULTI-PURPOSE LUBRICANTS, WHEEL WEIGHTS, FASTENERS, AND ADHESIVES.

TOTAL LABOR....	3023.45
TOTAL PARTS....	524.27
TOTAL SUBLET...	0.00
TOTAL G.O.G....	2.28
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	0.00
TOTAL TAX.....	43.25
TOTAL INVOICE $	**3593.25**

CUSTOMER SIGNATURE

ENVIRONMENTAL COMPLIANCE CHARGE

Maintaining and repairing your car inevitably involves the use of chemicals and generation of wastes (solvents, oils, caustics, lead, asbestos, etc.) that must be stored, managed and disposed of in strict compliance with federal, state and local environmental regulations. We support these regulations and also believe our customers do too because they help ensure a safer, healthier environment for everyone. Complying with these regulations increases the cost of service. Ordinarily, increased costs simply result in an increased hourly labor charge. This dealership has decided in lieu of raising its labor rate, to list a compliance charge on appropriate service bills because we believe our customers would be interested to know that they are helping to pay for a cleaner environment.

DISCLAIMER OF WARRANTIES

BY SIGNING, BUYER ACKNOWLEDGES AND AGREES THAT THE SELLER, EXPRESSLY DISCLAIMS ALL WARRANTIES WHETHER STATUTORY, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND WARRANTIES ARISING FROM COURSE OF DEALING OR USAGE OF TRADE. BUYER FURTHER AGREES THAT ALL EXPRESS WARRANTIES OR EXPRESS REPRESENTATIONS OF MATERIAL FACTS ARE CLEARLY SET FORTH UPON THIS AGREEMENT AND THAT NO WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF.

TERMS CASH UNLESS ARRANGEMENTS MADE

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X _____

NOTICE PURSUANT TO §70.001, Texas Property Code

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON, WHO IS OBLIGATED TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR AGREEMENT. I UNDERSTAND THAT THE VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.609, Texas Business and Commerce Code, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE MAKER OR DRAWER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

CLAIMS FOR WORK PERFORMED MUST BE MADE WITHIN 180 DAYS
OR 6,000 MILES WHICHEVER COMES FIRST FROM DATE OF WORK.

 CUSTOMER COPY | END OF INVOICE | 12:53pm

The Reynolds and Reynolds Company (Shelbyville) CC1135(1) Q (07/18)

PORSCHE

Porsche Austin

200 E. Hunland Dr. • Austin, TX 78752 • (512)371-1155 • 800-687-1747

PARTS HAS UNIQUE ACCESSORIES
FOR UNIQUE CARS
SEE OUR PARTS DEPARTMENT FOR DETAILS

[redacted]

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	
10057	SHEALEA GREER 800445	4895	02/17/20	P0CS82150

LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
205.00		150,140 /		

YEAR / MAKE / MODEL	DELIVERY DATE	DELIVERY MILES
03/PORSCHE/911/		

VEHICLE I.D. NO.	SELLING DEALER NO.	PRODUCTION DATE
WP0AA2994 3S622267		

F.T.E. NO.	R.O. NO.	R.O. DATE
		01/29/20

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS
		MO: 150178

LABOR & PARTS----------

J# 5+07P0Z STEER/SUSP BASE TECH(S):800387 600422 INTERNAL

CLIENT APPROVED BUMP STOP
FOUND LEFT AND RIGHT FRONT UPPER STRUT MOUNTS AND BEARING
WELL PAST WORN AND ARE COMING APART.
R&R BOTH FRONT STRUTS, DISASSEMBLE AND REPLACE LEFT AND
RIGHT UPPER STRUT MOUNTS, BEARINGS AND BUMP STOP.

PARTS------	QTY---	FP-NUMBER----------	DESCRIPTION----------	UNIT PRICE-	
JOB # 5	2	N-103-353-04	HEXAGON NUT		INTERNAL
JOB # 5	2	N-102-112-02	HEX-HEAD BOLT 12		INTERNAL
JOB # 5	1	999-084-445-01	LOCK NUT		INTERNAL
JOB # 5	1	996-343-015-04	SHOCK ABS. MOUNT		INTERNAL
JOB # 5	1	996-343-016-04	SHOCK ABS. MOUNT		INTERNAL
JOB # 5	2	996-343-501-00	ANGULAR CONTACT		INTERNAL
JOB # 5	2	996-343-525-00	SHOCK ABS. MOUNT		INTERNAL
JOB # 5	2	996-343-525-01	SHOCK ABS. MOUNT		INTERNAL
JOB # 5	2	996-343-523-00	SHOCK PLATE		INTERNAL
JOB # 5	2	999-084-449-09	NUT		INTERNAL
			JOB # 5 TOTAL PARTS		0.00
			JOB # 5 TOTAL LABOR & PARTS		0.00

J# 6+03P0Z BASE CODE ELECTRIC TECH(S):800422 205.00

ABS LIGHT COMES ON WHILE DRIVING.
FOUND BRAKE LIGHTS NOT WORKING. FOUND FUSE BLOWN, REPLACE
BLOWN FUSE AND RETEST. FOUND BRAKE LIGHT STAYING ON AT TIMES
AND THEN FUSE WILL BLOW.
REPLACE BRAKE LIGHT SWITCH AND RETEST. OPERATING AS
DESIGNED.

PARTS------	QTY---	FP-NUMBER----------	DESCRIPTION----------	UNIT PRICE-	
JOB # 6	3	999-607-085-00	FUSE 15A	1.54	4.62
			JOB # 6 TOTAL PARTS		4.62
			JOB # 6 TOTAL LABOR & PARTS		209.62

G.O.G. & SUPPLIES----------

JOB # 2	RUSH SHIPPING			2.28
JOB # 4	1.0	@	/UNIT	0.00
			TOTAL - GOG	2.28

MISC------	CODE--------	DESCRIPTION----------	CONTROL NO---------	
JOB # A	1PSSS	PO SHOP SUPPLIES INTERNAL		INTERNAL
			TOTAL - MISC	0.00

COMMENTS----------
++SHUTTLE++X07SZSWNX4:cc created 2020-01-27 02:08:00pm taken by
Reservations 2 5

CLAIMS FOR WORK PERFORMED MUST BE MADE WITHIN 180 DAYS
OR 6,000 MILES WHICHEVER COMES FIRST FROM DATE OF WORK.

ENVIRONMENTAL COMPLIANCE CHARGE

Maintaining and repairing your car inevitably involves the use of chemicals and generation of wastes (solvents, oils, caustics, lead, asbestos, etc.) that must be stored, managed and disposed of in strict compliance with federal, state and local environmental regulations. We support these regulations and also believe our customers do too because they help ensure a safer, healthier environment for everyone. Complying with these regulations increases the cost of service. Ordinarily, increased costs simply result in an increased hourly labor charge. This dealership has decided in lieu of raising its labor rate, to list a compliance charge on appropriate service bills because we believe our customers would be interested to know that they are helping to pay for a cleaner environment.

DISCLAIMER OF WARRANTIES

BY SIGNING, BUYER ACKNOWLEDGES AND AGREES THAT THE SELLER, EXPRESSLY DISCLAIMS ALL WARRANTIES WHETHER STATUTORY, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND WARRANTIES ARISING FROM COURSE OF DEALING OR USAGE OF TRADE. BUYER FURTHER AGREES THAT ALL EXPRESS WARRANTIES OR EXPRESS REPRESENTATIONS OF MATERIAL FACTS ARE CLEARLY SET FORTH UPON THIS AGREEMENT AND THAT NO WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF.

TERMS CASH UNLESS ARRANGEMENTS MADE

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X _____

NOTICE PURSUANT TO §70.001, Texas Property Code

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON, WHO IS OBLIGATED TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR AGREEMENT. I UNDERSTAND THAT THE VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.609, Texas Business and Commerce Code, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE MAKER OR DRAWER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

The Reynolds and Reynolds Company 7040/7041 CC/13621 Q 07/16

 [CONTINUED ON NEXT PAGE] 12:53pm

PORSCHE

Porsche Austin

200 E. Huntland Dr. • Austin, TX 78752 • (512)371-1155 • 800-687-1747

PARTS HAS UNIQUE ACCESSORIES
FOR UNIQUE CARS
SEE OUR PARTS DEPARTMENT FOR DETAILS

[redacted]

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE
10057	SHEALEA GREER 800445	4895	02/17/20 P0CS82150

[redacted]

LABOR RATE	LICENSE NO.	MILEAGE	COLOR	STOCK NO.
205.00		150,140 /		

YEAR / MAKE / MODEL	DELIVERY DATE	DELIVERY MILES
03/PORSCHE/911/		

VEHICLE I.D. NO.	SELLING DEALER NO.	PRODUCTION DATE
WP0AA29943S622267		

F.T.E. NO.	R.O. NO.	R.O. DATE
		01/29/20

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS
		MO: 150178

LABOR & PARTS----------

J# 1 02POZ — CHECK ENGINE LAMP — TECH(S):800387 800422 — 2500.00

CLIENT STATES ENGINE LIGHT WAS ON BUT CAME BACK. APPROVED 1 HOUR DIAG. ANYTHING OVER NEED TO REQUEST APPROVAL FROM CLIENT.
FOUND LARGE OIL LEAK AT BANK 2 CRANKCASE VENT LINE.
R&R ENGINE/TRANS ASSEMBLY. REPLACE BANK 1 TO BANK 2 CRANK CASE CONNECTION PIPE AND OIL SEPARATOR. CLEAN OIL RESIDUE FROM ENGINE. RETEST AND FOUND OPERATING AS DESIGNED.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 1	1	996-107-026-51	OIL-VAP,SEPARATO	129.56	129.56
JOB # 1	1	996-107-147-55	BREATHER HOSE	135.45	135.45
JOB # 1	1	999-707-446-40	RUBBER O-RING	1.85	1.85
JOB # 1	6	997-110-247-00	RUBBER GASKET, I	9.85	59.10
JOB # 1	1	996-107-147-59	VENT LINE, CYL.4	45.63	45.63
JOB # 1	1	999-707-534-41	O-RING	3.65	3.65
JOB # 1	2	000-043-305-74	PENTOSIN (1LTR)	18.95	37.90
JOB # 1	2	000-043-305-75	ANTIFREEZE (3.78	32.75	65.50
			JOB # 1 TOTAL PARTS		478.64
			JOB # 1 TOTAL LABOR & PARTS		2978.64

J# 2 00POZMPI — MULTIPOINT INSPECTIO — TECH(S):800422 — 0.00

PERFORM MULTIPOINT INSPECTION
PERFORMED MULTIPOINT INSPECTION

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 2	1	996-343-301-02	ADDITIONAL SPRIN	18.65	18.65
		RUSH SHIPPING			
JOB # 2	1	996-613-113-02	PEDAL SWITCH, BR	22.36	22.36
			JOB # 2 TOTAL PARTS		41.01
			JOB # 2 TOTAL LABOR & PARTS		41.01

J# 3+09POZ — ALIGN BASE CODE — TECH(S):800422 — 299.95

CLIENT APPROVED ALIGNMENT
PERFORM SUSPENSION ALIGNMENT.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
			JOB # 3 TOTAL PARTS		0.00
			JOB # 3 TOTAL LABOR & PARTS		299.95

J# 4+12POZE — EMISSION STICKER — TECH(S):800161 — 18.50

CUSTOMER REQUESTS STATE EMISSION INSPECTION TEST
INSURANCE EXPIRATION DATE:
ANNUAL EMISSION AND SAFETY INSPECTION.
COMPLETED ANNUAL EMISSION AND SAFETY INSPECTION.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
			JOB # 4 TOTAL PARTS		0.00
			JOB # 4 TOTAL LABOR & PARTS		18.50

CLAIMS FOR WORK PERFORMED MUST BE MADE WITHIN 180 DAYS OR 6,000 MILES WHICHEVER COMES FIRST FROM DATE OF WORK.

ENVIRONMENTAL COMPLIANCE CHARGE

Maintaining and repairing your car inevitably involves the use of chemicals and generation of wastes (solvents, oils, caustics, lead, asbestos, etc.) that must be stored, managed and disposed of in strict compliance with federal, state and local environmental regulations. We support these regulations and also believe our customers do too because they help ensure a safer, healthier environment for everyone. Complying with these regulations increases the cost of service. Ordinarily, increased costs simply result in an increased hourly labor charge. This dealership has decided in lieu of raising its labor rate, to list a compliance charge on appropriate service bills because we believe our customers would be interested to know that they are helping to pay for a cleaner environment.

DISCLAIMER OF WARRANTIES

BY SIGNING, BUYER ACKNOWLEDGES AND AGREES THAT THE SELLER, EXPRESSLY DISCLAIMS ALL WARRANTIES WHETHER STATUTORY, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND WARRANTIES ARISING FROM COURSE OF DEALING OR USAGE OF TRADE. BUYER FURTHER AGREES THAT ALL EXPRESS WARRANTIES OR EXPRESS REPRESENTATIONS OF MATERIAL FACTS ARE CLEARLY SET FORTH UPON THIS AGREEMENT AND THAT NO WARRANTIES OR REPRESENTATIONS, EXPRESS OR IMPLIED, EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF.

TERMS CASH UNLESS ARRANGEMENTS MADE

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

X _____

NOTICE PURSUANT TO §70.001, Texas Property Code

I AM THE PERSON OR AGENT ACTING ON BEHALF OF THE PERSON, WHO IS OBLIGATED TO PAY FOR THE REPAIR OF THE MOTOR VEHICLE SUBJECT TO THE REPAIR AGREEMENT. I UNDERSTAND THAT THE VEHICLE IS SUBJECT TO REPOSSESSION IN ACCORDANCE WITH §9.609, Texas Business and Commerce Code, IF PAYMENT FOR THE REPAIR OF THE MOTOR VEHICLE BY A CHECK, MONEY ORDER, OR A CREDIT CARD TRANSACTION IS STOPPED, DISHONORED BECAUSE OF INSUFFICIENT FUNDS, NO FUNDS, OR BECAUSE THE MAKER OR DRAWER HAS NO ACCOUNT OR THE ACCOUNT UPON WHICH IT IS DRAWN OR THE CREDIT CARD ACCOUNT HAS BEEN CLOSED.

Signature of Person Responsible or Agent for Person Responsible

The Reynolds and Reynolds Company ©MMVIII-HE CC/T3821 Q (07/18)

 [CONTINUED ON NEXT PAGE] 12:53pm