Nordkuste Performance
(216) 586-6141
mike@nordkuste.com
4869 Van Epps Rd, Independence, OH, USA, 44131

NORDKÜSTE

Invoice # 51852

Against Estimate#: 12447
Created: Dec 10, 2024
Invoiced: Mar 13, 2025

2002 BMW M3 Base
VIN: WBSBR93412EX24022
Mileage: 68921 miles
License Plate:

Rear Subframe Reinforcement Service

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Subframe R&R	Perform rear E46 Subframe reinforcement service. Includes R&R of rear subframe, fuel tank and performing alignment post service.	$1,475.00	1	$1,475.00
2	Subframe Kit	Reddish MS rear subframe kit	$225.00	1	$225.00
3	Paint	Weldable primer paint	$17.00	1	$17.00
4	Paint	Paint	$8.50	1	$8.50

Amount: $1,725.50 | Disc: $0.00 | Subtotal: $1,725.50

(Optional Services) Rear Bushings, Ball Joints & Adjustable Arms

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Custom Services	Replace rear subframe bushings, trailing arm bushings, diff bushings, all ball joints and install adjustable rear camber arms.	$139.00	3.3	$458.70
2	Suspension Kit	Rear suspension kit. Includes OEM subframe and differential bushings. Eibach adjustable camber arms. Lemforder ball joints and trailing arm bushings.	$952.56	1	$952.56

Amount: $1,411.26 | Disc: $0.00 | Subtotal: $1,411.26

(Optional Service) Internal RACP Repair Service

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Custom Services	Internal RACP welding / repair service. Includes removal of rear seats and all trunk components. Requires cutting into trunk floor for access. Includes rust proofing & painting prior to reassembly.	$850.00	1	$850.00
2	Additional Time	Additional labor time approved by customer for additional work required convertible models	$250.00	1	$250.00

Amount: $1,100.00 | Disc: $0.00 | Subtotal: $1,100.00

Noise Diagnostics

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Diagnostics	Customer states he hears an engine noise. Mostly when engine is cold or upon start up. Diagnose and repair	$139.00	0.5	$69.50

Amount: $69.50 | Disc: $0.00 | Subtotal: $69.50

Replace Idler & Tensioner Pulleys

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Repair	Remove and replace both the idler and belt tensioner pulleys	$139.00	0.7	$97.30

Nordkuste Performance
(216) 586-6141
mike@nordkuste.com
4869 Van Epps Rd, Independence, OH, USA, 44131

NORDKÜSTE PERFORMANCE

Invoice # 51852

Against Estimate#: 12447
Created: Dec 10, 2024
Invoiced: Mar 13, 2025

2	Pulley	Idler Pulley	$35.11	1	$35.11
3	Pulley	Belt Tensioner Pulley	$33.35	1	$33.35
			Amount: $165.76	Disc: $0.00	Subtotal: $165.76

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature: _____

Service Amount	**$4,472.02**
Part	$1,271.52
Labor	$3,200.50
Total RO Fees	
Shop Supplies	$14.50
Subtotal	**$4,486.52**
Taxes	
Cuyahoga County (8%)	$239.76
Grand total	**$4,726.28**
Paid to date	**$4,726.28**
Remaining Balance	**$0.00**

Nordkuste Performance
(216) 586-6141
mike@nordkuste.com
4869 Van Epps Rd, Independence, OH, USA, 44131

Estimate # 12447

Created: Dec 10, 2024

2002 BMW M3 Base
VIN: WBSBR93412EX24022
Mileage: 68921 miles
License Plate:

Rear Subframe Reinforcement Service

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Subframe R&R	Perform rear E46 Subframe reinforcement service. Includes R&R of rear subframe, fuel tank and performing alignment post service.	$1,475.00	1	$1,475.00
2	Subframe Kit	Reddish MS rear subframe kit	$225.00	1	$225.00
3	Paint	Weldable primer paint	$17.00	1	$17.00
4	Paint	Paint	$8.50	1	$8.50
			Amount: $1,725.50	Disc: $0.00	Subtotal: $1,725.50

(Optional Services) Rear Bushings, Ball Joints & Adjustable Arms

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Custom Services	Replace rear subframe bushings, trailing arm bushings, diff bushings, all ball joints and install adjustable rear camber arms.	$139.00	3.3	$458.70
2	Suspension Kit	Rear suspension kit. Includes OEM subframe and differential bushings. Eibach adjustable camber arms. Lemforder ball joints and trailing arm bushings.	$952.56	1	$952.56
			Amount: $1,411.26	Disc: $0.00	Subtotal: $1,411.26

(Optional Service) Internal RACP Repair Service

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Custom Services	Internal RACP welding / repair service. Includes removal of rear seats and all trunk components. Requires cutting into trunk floor for access. Includes rust proofing & painting prior to reassembly.	$850.00	1	$850.00
2	Additional Time	Additional labor time approved by customer for additional work required convertible models	$250.00	1	$250.00
			Amount: $1,100.00	Disc: $0.00	Subtotal: $1,100.00

Noise Diagnostics

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Diagnostics	Customer states he hears an engine noise. Mostly when engine is cold or upon start up. Diagnose and repair	$139.00	0.5	$69.50
			Amount: $69.50	Disc: $0.00	Subtotal: $69.50

Replace Idler & Tensioner Pulleys

Authorized

Item	Name	Description	Price	Qty/Hrs	Amount
1	Repair	Remove and replace both the idler and belt tensioner pulleys	$139.00	0.7	$97.30
2	Pulley	Idler Pulley	$35.11	1	$35.11

Nordkuste Performance
(216) 586-6141
mike@nordkuste.com
4869 Van Epps Rd, Independence, OH, USA, 44131

NORDKÜSTE PERFORMANCE

Estimate # 12447

Created: Dec 10, 2024

3	Pulley	Belt Tensioner Pulley	$33.35	1	$33.35
			Amount: $165.76	Disc: $0.00	Subtotal: $165.76

I hereby authorize the above repair work to be done along with procurement of all necessary materials.

Nordkuste Performance may operate the above vehicle for the purposes of testing, inspection or delivery at my risk. Nordkuste Performance will not be held responsible for any loss or damage to the vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond the control of Nordkuste Performance.

In the event legal action is necessary to enforce this contract, I understand that I am solely responsible for all costs.

Service Amount	**$4,472.02**
Part	$1,271.52
Labor	$3,200.50
Total RO Fees	
Shop Supplies	$14.50
Subtotal	**$4,486.52**
Taxes	
Cuyahoga County (8%)	$239.76
Grand total	**$4,726.28**
Paid to date	**$1,200.00**
Remaining Balance	**$3,526.28**

Signature: _____

Nordkuste Performance
4869 Van Epps Rd
Brooklyn Heights, OH 44131 US
2165866141
mike@nordkuste.com
www.Nordkuste.com

Invoice

NORDKÜSTE
PERFORMANCE

BILL TO

E46 BMW M3
Mileage: 61,696
VIN: WBSBR93412EX24022

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
50071	07/22/2022	$3,398.87	07/22/2022	Due on receipt	

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
Discount	Acura GS-R	1	-3,500.00	-3,500.00
Labor	Perform SMG to manual transmission swap	17	99.00	1,683.00T
Labor	Fabrication labor. Custom transmission brace, shorten shifter rod and modified transmission shift arm	3	99.00	297.00T
Part	30k original mile M3 manual transmission	1	2,200.00	2,200.00T
Part	Clutch pedal assembly kit	1	68.57	68.57T
Part	Clutch cylinder refresh kit	1	238.70	238.70T
Part	Clutch Switch	1	61.62	61.62T
Part	Short Shifter kit w/ Alcantara boot and weighed shifter	1	351.97	351.97T
Part	Shifter level circlip	4	1.89	7.56T
Part	Cruise control clutch lead	1	13.94	13.94T
Part	Clip	1	0.96	0.96T
Part	Shifter arm bracket	1	31.99	31.99T
Part	Pedal Grommet	3	3.46	10.38T
Part	Shifter rod joint	1	60.95	60.95T
Part	Bearing pin	1	6.46	6.46T
Part	Shifter rubber insulator boot	1	39.14	39.14T
Part	Shifter bushing	1	9.44	9.44T
Part	Selector rod	1	78.12	78.12T
Part	Shifter Arm	1	51.89	51.89T
Part	Shifter rod coupling bushing	1	4.73	4.73T
Part	Shifter lever base	1	49.35	49.35T
Part	Locking ring	1	0.97	0.97T

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
Part	Shifter arm bushing	1	19.59	19.59T
Part	Plastic washer	8	2.89	23.12T
Part	Dowel pin	1	1.90	1.90T
Part	Clutch line retention kit	1	12.45	12.45T
Part	Circlip	3	1.86	5.58T
Part	Transmission shifting arm	1	50.33	50.33T
Part	Transmission rear adapter support	1	57.38	57.38T
Part	Clutch Kit	1	326.84	326.84T
Part	Flywheel bolts	8	5.71	45.68T
Part	Pressure plate bolt	6	3.23	19.38T
Part	Rear crankshaft seal	1	25.26	25.26T
Part	Transmission fluid 75w-80	1.50	19.22	28.83T
Labor	Replace battery	0.20	99.00	19.80T
Part	Battery w/36 month warranty	1	205.00	205.00T
Labor	Alignment	1	149.00	149.00T
Labor	Mount and balance tires	4	22.50	90.00T
Services	Waste tire disposal fee	4	5.99	23.96T
Shop Supplies	Shop supplies / waste fluid fee	2	8.50	17.00T

SUBTOTAL	2,887.84
TAX	511.03
TOTAL	3,398.87
BALANCE DUE	**$3,398.87**

Nordkuste Performance
4869 Van Epps Rd
Brooklyn Heights, OH 44131 US
2165866141
mike@nordkuste.com
www.Nordkuste.com

Estimate

NORDKÜSTE
PERFORMANCE

ADDRESS
E46 BMW M3 Mileage: VIN:

ESTIMATE #	DATE
1372	11/08/2021

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
Discount	Acura GS-R	1	-3,500.00	-3,500.00
Labor	Perform SMG to manual transmission swap	17	99.00	1,683.00T
Part	30k original mile M3 manual transmission	1	2,200.00	2,200.00T
Part	Clutch pedal assembly kit	1	68.57	68.57T
Part	Clutch cylinder refresh kit	1	238.70	238.70T
Part	Clutch Switch	1	61.62	61.62T
Part	Short Shifter kit w/ Alcantara boot and weighed shifter	1	351.97	351.97T
Part	Shifter level circlip	4	1.89	7.56T
Part	Cruise control clutch lead	1	13.94	13.94T
Part	Clip	1	0.96	0.96T
Part	Shifter arm bracket	1	31.99	31.99T
Part	Pedal Grommet	3	3.46	10.38T
Part	Shifter rod joint	1	60.95	60.95T
Part	Bearing pin	1	6.46	6.46T
Part	Shifter rubber insulator boot	1	39.14	39.14T
Part	Shifter bushing	1	9.44	9.44T
Part	Selector rod	1	78.12	78.12T
Part	Shifter Arm	1	51.89	51.89T
Part	Shifter rod coupling bushing	1	4.73	4.73T
Part	Shifter lever base	1	49.35	49.35T
Part	Locking ring	1	0.97	0.97T
Part	Shifter arm bushing	1	19.59	19.59T

SERVICE	DESCRIPTION	QTY	RATE	AMOUNT
Part	Plastic washer	8	2.89	23.12T
Part	Dowel pin	1	1.90	1.90T
Part	Clutch line retention kit	1	12.45	12.45T
Part	Circlip	3	1.86	5.58T
Part	Transmission fluid	1		0.00T
Shop Supplies	Shop supplies / waste fluid fee	2	8.50	17.00T

SUBTOTAL	1,549.38
TAX	403.95
TOTAL	**$1,953.33**

Accepted By

Accepted Date

LAROW AUTOMOTIVE

PERSONALIZED BMW SERVICE & REPAIRS

112 WINOLA CT.
GREENSBORO, NC 27409
(336) 587-1670

REPAIR WORK ORDER

Date 12-20-19

Name

Address

Phone

Year 02 | Make BMW | Model M3

VIN EX 24022 | Odometer In | Odometer Out 60,100

Parts	Qty	Amount	Description Of Work	Labor	Amount
Exhaust Vanos Hub	1	699.00	Remove Vanos Unit Replace failed Exhaust Hub and Disc. Installed		
Vanos Oil pump Drive Disc.	1	250.00	Bolt upgrade Kit. Timed		
Upgrade Bolt Kit	1	40.00	Engine and Re-assembled	8.0	800.00
Valve Cover Gasket	1	76.38			
Vanos Gasket	1	15.74			
Solenoid Gasket	1	39.33			
Parts Total		1,120.45		Labor Total	800.00
				Sublet Total	
				Diagnostic	
				Subtotal	1,920.45
				Tax	129.63
				TOTAL	2,050.08

YOU ARE HEREBY AUTHORIZED TO MAKE THE REPAIRS MENTIONED ABOVE AND I AGREE TO PAY ALL APPLICABLE CHARGES. A 25% LABOR SURCHARGE WILL APPLY TO ALL CUSTOMER SUPPLIED PARTS. VEHICLES LEFT MORE THAN 3 DAYS AFTER COMPLETION OF THE REPAIRS WILL BE SUBJECT TO A STORAGE CHARGE.

X

AUTHORIZED SIGNATURE

DATE

CUSTOMER #: 53028

109481

INVOICE

PAGE 1

FLOW BMW

2565 Peters Creek Parkway
Winston-Salem, NC 27127
Phone: (336) 788-3333
www.flowauto.com

SERVICE ADVISOR: 93042 KENNY STARNES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
CARBON BLA	02	BMW M3CIC	WBSBR93412EX24022	DKN3241	53485/53485	T798

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN02 IS 01JAN02 DD			13:00 13MAR17		0.00	CC	10MAR17

R.O. OPENED	READY	OPTIONS:
11:36 10MAR17	12:11 10MAR17	

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A ELECTRICAL REPAIRS-srs lite is on & off since airbag
replacement-seems to be worse when cold & goes out after warms
up-check history-advise
ELE ELECTRICAL REPAIRS-srs lite is on & off since
airbag replacement-seems to be worse when
cold & goes out after warms up-check
history-advise
93187 INS (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

53485 srs lite not on at time of inspection-performed fault
test-found one time fault for p/s front seat occupancy detector
mat-cleared fault & did not return-not related to airbag replacement
****

EST: 0.00 10MAR17 11:36 SA: 93042

see Kenny

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***SHOP SUPPLY COSTS:** We have added a charge equal to 7.5% of the total cost of labor and parts, not to exceed $35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

DealerCAP 2014 CDK Global, LLC (08/14) SERVICE INVOICE TYPE 2 - 25120 - "AS-IS" - NC - 5036457

CUSTOMER COPY

CUSTOMER #: 53028

PAID MAR 08 2017

109325

INVOICE

PAGE 1

FLOW BMW

2565 Peters Creek Parkway
Winston-Salem, NC 27127
Phone: (336) 788-3333
www.flowauto.com

SERVICE ADVISOR: 93042 KENNY STARNES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
CARBON BLA	02	BMW M3CIC	WBSBR93412EX24022	DKN3241	53363/53365	T754

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN02 IS 01JAN02 DD			13:45 08MAR17		0.00	CC	07MAR17

R.O. OPENED	READY	OPTIONS:
09:11 07MAR17	13:29 07MAR17	

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A RECALLS SIB#651115 RECALL
CAUSE: .
RCL RECALLS SIB#651115 RECALL
93187 WB (N/C)
1 32-30-6-877-590 HUB CAP, AIRBAG:889700 (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
53363 air bag
Defect Code: 00 32 39 02 00

Labor Operation: Labor Allowance: Description:
00 64 071 5 FRU Replace the driver-side front Air bag (Main work)
16b2691t0028

****

B RECALLS-SIB#651513 RECALL
CAUSE: .
RCL RECALLS-SIB#651513 RECALL
93187 WB (N/C)
1 72-12-9-394-543 AIRBAG FOR FRONT
PASSENGER:889700 (N/C)
1 51-45-8-146-760 FASTENING ELEMENTS:51409945 (N/C)
2 07-11-9-905-374 SELF-LOCKING COLLAR
NUT:072000 (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
53363 air bag
Defect Code: 00 72 33 01 00

Labor Operation: Labor Allowance: Description:
00 61 067 Refer to KSD2 Replace the front passenger?s airbag module
(includes disconnecting and connecting battery negative cable)
15b1123t3982L

****

C FULL DETAIL OF CUSTOMERS VEHICLE
DET-FULL-C FULL DETAIL OF CUSTOMERS VEHICLE
93076 CPB 174.95 174.95

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

*SHOP SUPPLY COSTS: We have added a charge equal to 7.5% of the total cost of labor and parts, not to exceed $35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 53028

109325

INVOICE

PAGE 2

FLOW BMW

2565 Peters Creek Parkway
Winston-Salem, NC 27127
Phone: (336) 788-3333
www.flowauto.com

SERVICE ADVISOR: 93042 KENNY STARNES

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
CARBON BLA	02	BMW M3CIC	WBSBR93412EX24022	DKN3241	53363/53365	T754

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN02 IS 01JAN02 DD			13:45 08MAR17		0.00	CC	07MAR17

R.O. OPENED	READY	OPTIONS:
09:11 07MAR17	13:29 07MAR17	

LINE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
DSS DETAIL SHOP SUPPLY		15.00	15.00

PARTS: 0.00 LABOR: 174.95 OTHER: 15.00 TOTAL LINE C: 189.95

****

EST: 174.95 07MAR17 09:11 SA: 93042

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

***SHOP SUPPLY COSTS:** We have added a charge equal to 7.5% of the total cost of labor and parts, not to exceed $35.00, to the Repair Order for shop supplies used in connection with this repair.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	174.95
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	15.00
TOTAL CHARGES	189.95
LESS INSURANCE	0.00
SALES TAX	12.82
PLEASE PAY THIS AMOUNT	202.77

DealerCAR 2014 CDK Global, LLC (08/14) SERVICE INVOICE TYPE 2 - 25/20 "AS-IS" - NC - 3036457

CUSTOMER COPY

FIRST QUALITY AUTO

605 EDWARDIA DRIVE
GREENSBORO, NC 27409
(336)299-8535

Repair Order # **11739**
Date Printed : 8/9/16
Page : 1
Center : 1

Customer :
Address :
City : GREENSBORO, NC 27
Phone 1 : (336) --- **Ext :**
Phone 2 : (336) --- **Ext :**

Vehicle : 2002 BMW M3
License : **Colr :**
VIN :
Engine : **Trans :** AUTO
Mileage : **Type :**

Parts

Quan	Part Number	Description	Price
1.00	258656	BLOWER MTR RES	124.00

Labor

Op	Tech	Description	Time	Charge
		REPLACE BLOWER MOTOR RES		85.00

OK	Bad	Recommendation	OK	Bad	Recommendation	OK	Bad	Recommendation

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for damage or articles left in car in case of fire, theft or any other cause beyond our control.
WARRANTY IS 6 MONTHS OR 6000 MILES WHICH EVER OCCURS FIRST.

SIGNATURE----------

Labor :	$85.00
Parts :	$124.00
Sublet :	$0.00
Other Fees :	$0.00
Shop/Enviro	$6.27
Subtotal :	$215.27
Sales Tax :	$14.53
Total :	$229.80
Paid :	$229.80
Due :	$0.00

Paid By : MSTR CHARG VISA
Pay Ref :