



Steinels Autowerks  
8295 Darrow Road  
Twinsburg, OH 44087  
(330) 425-8582  
Steinels.com

Invoice #5304

Created: 6/24/2024  
Invoiced: 7/24/2024  
Payment Term: On Receipt  
Service Writer: Jason K

1999 Porsche 911 Carrera (Silver)

VIN: WP0AA2992XS622743  
Mileage In: 49,150  
Mileage Out: 49,165  
PSI: FL 36 FR 36 RL 42 RR 42

Customer Comments	Recommendations
Airbag light for pass buckle	

Engine (Repair)				
Description	Price	QTY	HRS	Subtotal
1 Engine Assembly R&I (RWD, With Air Conditioning)			10.6	\$1,749.00
2 Camshaft R&R (Left, With Air Conditioning)			9.8	\$1,617.00
3 Valve Spring / 996	\$23.87	1		\$23.87
4 Elring Intake Manifold Gasket - Manifold to Head Note: Gasket for Intake Manifold.	\$5.19	2		\$10.38
5 Elring Intake Manifold Gasket - Manifold to Intake Distributor Note: Gasket for Intake Manifold.	\$8.24	6		\$49.44
6 Elring Cover Piece with Seal for Camshaft Adjuster Solenoid on Valve Cover Note: Engine Variable Valve Timing (VVT) Adjuster Seal.	\$18.85	2		\$37.70
7 Elring Cylinder Head Plug (Camshaft End Plug) Note: Engine Cylinder Head Plug.	\$12.54	3		\$37.62
8 Victor Reinz O-Ring for Engine Oil Pumps (Secondary Pumps) 95 X 2.5 mm Note: Engine Oil Pump O-Ring.	\$3.73	2		\$7.46
9 Elring Gasket - Exhaust Manifold to Head Note: Exhaust Manifold Gasket.	\$8.66	2		\$17.32
10 Victor Reinz Timing Chain Rail O-Ring Note: Engine Timing Chain Guide Gasket.	\$10.59	2		\$21.18
11 Thread Recovery / 10 Exhaust Bolts			6	\$990.00
12 Elring Exhaust Manifold Bolt (8 X 28 mm) Note: Exhaust Manifold Bolt.	\$1.64	12		\$19.68
13 15 W 50 Mobil One Part #: 15w50Mobil1	\$11.96	7		\$83.72
14 Oil Filter Part #: 996-107-225-53	\$13.50	1		\$13.50
15 Hydraulic Fluid / Pentosin CHF 202	\$20.91	1		\$20.91
16 Air Conditioning System Evacuate & Recharge			1.4	\$231.00
17 R134 Refrigerant Part #: R134	\$15.99	2.2		\$35.18



Steinels Autowerks  
8295 Darrow Road  
Twinsburg, OH 44087  
(330) 425-8582  
Steinels.com

Invoice #5304

Created: 6/24/2024  
Invoiced: 7/24/2024  
Payment Term: On Receipt  
Service Writer: Jason K

#### Engine (Repair)

18	Genuine Porsche Oil Separator <i>Note: Engine Oil Separator.</i>	\$169.40	1	\$169.40
19	Genuine Porsche Timing Chain Rail Set for Solenoid Actuated Chain Adjuster <i>Note: Guide for the timing chain.</i>	\$61.49	2	\$122.98
EPA (1%): \$6.70    Shop Supplies (3%): \$137.61    Tax (6.75%): \$354.87		Total: \$5,756.52		

#### Engine (Service Additions)

	Description	Price	QTY	HRS	Subtotal
1	Camshaft R&R (Right, additional)			5.1	\$841.50
2	Water Pump R&R (With Thermostat) Reduced			2.8	\$462.00
3	Wahler Thermostat with Cover and Gasket <i>Note: An Engine Coolant Thermostat only, housing not included.</i>	\$91.47	1		\$91.47
4	Continental Belt - 6K X 2115 <i>Note: A component of the external engine that transfers power to accessory pulleys by rotation.</i>	\$26.96	1		\$26.96
5	Pierburg Water Pump <i>Note: Main Engine Water Pump.</i>	\$332.18	1		\$332.18
6	Coolant / Factory <i>Note: Porsche Coolant</i>	\$65.26	2.1		\$137.05
7	Install LN Engineering IMS Solution			4.5	\$742.50
8	IMS Solution - LN Engineering	\$1,637.16	1		\$1,637.16
9	Stabilizer Bar Link R&R (Front, Both Sides)			0.5	\$82.50
10	Pollen Filter <i>Part #: 997-571-219-01</i>	\$36.42	1		\$36.42
EPA (1%): \$22.61    Shop Supplies (3%): \$63.86    Tax (6.75%): \$296.31					<b>Total: \$4,772.52</b>

Thanks for choosing Steinels!

Signature \_\_\_\_\_

Parts .....	\$2,931.58
Labor .....	\$6,715.50
Subtotal .....	\$9,647.08
Shop Supplies .....	\$201.47
EPA .....	\$29.31
Tax .....	\$651.18
Grand Total .....	\$10,529.04
Paid To Date .....	(\$10,529.04)

**REMAINING BALANCE \$0.00**

#### Payments

2/19/2025

Steinels Autowerks  
Powered by Shopmonkey.io

Page 2 of 5