



CAE Motorsport
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
CAEmotorsport.com

Invoice #2329

Created: 4/24/2025 02:54 PM EDT
Invoiced: 4/24/2025 04:52 PM EDT
Payment Term: Net 10
Payment Due: 05/04/2025
Service Writer: Tom Lerich

Switchcars Inc

1521 Highland Road
Twinsburg, OH 44087
Mobile: (216) 453-0507
info@switchcars.com

2002 PORSCHE 911 Turbo

VIN: WP0AB29912S685547
Mileage In: 49,973
Mileage Out: 49,973

Recommendations

Coolant pipes are not pinned

Radio display does not work

Vehicle Inventory Inspection

	Description	Price	QTY	HRS	Subtotal
1	Vehicle Inventory Inspection			2	\$180.00
2	Getgo 92	\$40.02	1		\$40.02
3	Pressure Test Cooling System			0.5	\$45.00
4	Porsche Engine Coolant/Antifreeze <i>Note: Genuine Porsche</i>	\$36.49	0.25		\$9.12
5	Pentosin CHF 11S	\$11.00	1		\$11.00
Shop Supplies (5%): \$11.25				Total:	\$296.39

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

Parts	\$60.14
Labor	\$225.00
Subtotal	\$285.14
Shop Supplies	\$11.25
Tax	\$0.00
Grand Total	\$296.39
Paid To Date	(\$0.00)

REMAINING BALANCE	\$296.39
--------------------------	-----------------

Authorizations

In Person by Switchcars Inc 4/24/2025 at 4:52 PM EDT	+ Vehicle Inventory Inspection	\$296.39
---	--------------------------------	----------



CAE Motorsport
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
CAEmotorsport.com

Inspection #2329

Switchcars Inc
1521 Highland Road
Twinsburg, OH 44087
Mobile: (216) 453-0507
info@switchcars.com

2002 PORSCHE 911 Turbo
VIN: WP0AB29912S685547
Mileage In: 49,973
Mileage Out: 49,973

Inventory Inspection

Inspected: 04/24/2025

	Item	Green	Yellow	Red	N/A
1	Read Out Diagnostic Codes		✓		
	Note/Recommendation: Codes P0420 and P0430 found. Converter efficiency both banks				
2	Engine Oil	✓			
	Note/Recommendation:				
3	Brakes/Brake Pad Thickness 3mm Minimum	✓			
	Note/Recommendation: F 7mm R 6mm				
4	Brake Fluid Humidity Test/3% Maximum	✓			
	Note/Recommendation: 1%				
5	Tires Tread Depth/Date Stamp		✓		
	Note/Recommendation: Tires are OLD!!! F 8/32nds, 0217 R 6.5/32nds, 4516, 4416				
6	Spare Tire Condition And Air Pressure				✓
	Note/Recommendation:				
7	Wheel Lock Present? Check For Compatibility				✓
	Note/Recommendation:				
8	Convertible Top/Targa Top/Pano/Sunroof Operation/Sunshades	✓			
	Note/Recommendation:				
9	Steering/Suspension/Wheel Bearings	✓			

Note/Recommendation:				
10	Transmission Fluid Level (if applicable)/Fluid Leaks/Drive Shaft Flex Joint(s) Guibo(s)	✓		
Note/Recommendation:				
11	Drivetrain Fluid Leaks-Front And Rear Differentials/Transfer Case/CV Boot Condition	✓		
Note/Recommendation:				
12	Battery/Inspect For Battery Vent Tube Where Applicable/Inspect And Clean Water Drains Near Battery Where Applicable	✓		
Note/Recommendation:				
13	Exhaust/Muffler/Clamps	✓		
Note/Recommendation:				
14	Engine Belts	✓		
Note/Recommendation:				
15	Coolant Level/Coolant Hoses	✓		
Note/Recommendation:				
16	Power Steering Fluid Condition And Level/Power Steering Hoses			
Note/Recommendation:				
17	Electric Power Steering Condition			✓
Note/Recommendation:				
18	Power/Manual Seat Operations/Check Heating And Cooling Where Applicable	✓		
Note/Recommendation:				
19	Power Side Mirror Movement Functions/Heating/Folding	✓		
Note/Recommendation:				
20	Gas Cap Seal	✓		
Note/Recommendation:				
21	Air Filter	✓		

Note/Recommendation:				
22	Cabin Filter	✓		
Note/Recommendation:				
23	Climate Control (A/C included)	✓		
Note/Recommendation:				
24	Radio Reception/Volume Check		✓	
Note/Recommendation: <i>Dispaly does not work. Volume is fine</i>				
25	Steering Wheel Button Function			✓
Note/Recommendation:				
26	Lights (head, brake, turn)	✓		
Note/Recommendation:				
27	Interior Lighting	✓		
Note/Recommendation:				
28	Wipers	✓		
Note/Recommendation:				
29	Locks/Keys	✓		
Note/Recommendation:				
30	Horn	✓		
Note/Recommendation:				
31	Headliner Condition	✓		
Note/Recommendation:				
32	Clean Front And/Or Rear Air Ducts Of Debris	✓		
Note/Recommendation:				
33	Porsche Flat 6 Engines. Most 911/Cayman/Boxster 1999-2010. Are The Ignition Coils Updated?	✓		
Note/Recommendation: <i>Updated</i>				



CAE Motorsport
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
CAEmotorsport.com

Inspection #2329

34	Porsche Battery Cavity Water Drains	✓			
Note/Recommendation:					
Totals		26	3	0	4