



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2094

Created: 10/29/2024 at 3:19PM
 Invoiced: 10/29/2024 at 4:24PM
 Payment Term: Net 10
 Payment Due: 11/08/2024
 Service Writer: Tom Lerich

Switchcars Inc
 1521 Highland Road
 Twinsburg, OH 44087
 Office: (216) 453-0507
 info@switchcars.com

2011 PORSCHE 911
 VIN: WP0AC2A94BS783061
 Mileage In: 18,340 mi
 Mileage Out: 18,340 mi
 PSI: FL 31 FR 31 RL 35 RR 35

Recommendations

Akrapovic rear carbon valance. Stock exhaust
 Sticky radio knobs

Vehicle Inventory Inspection

Description	Price	QTY	HRS	Subtotal
Labor: Vehicle Inventory Inspection			1.5	\$135.00
Labor: Repair Battery Vent/Tightened Battery Terminals			0.3	\$27.00
Labor: Recovered AC Service Caps Within Battery Area Water Drains			0.3	\$27.00
Part: 2032 Battery	\$3.30	1		\$3.30
			Shop Supplies (5%): \$9.45	Total: \$201.75

LOF

Description	Price	QTY	HRS	Subtotal
Labor: LOF/GT3RS Car			1	\$90.00
Labor: R & R Cabin Filter			0.3	\$27.00
Labor: R & R Engine Air Filter			0.5	\$45.00
Part: Hengst Oil Filter	\$12.96	1		\$12.96
Part: Mobil1 5W-40 Euro Full Synthetic Engine Oil for Water-Cooled Porsches	\$7.91	9.5		\$75.15
Part: Bosch Wiper Blade Set	\$30.20	1		\$30.20
Part: Mann Cabin Filter	\$25.76	1		\$25.76
Part: Mahle Air Filter	\$78.17	1		\$78.17
			Shop Supplies (5%): \$8.10	Total: \$392.34

Tire Replacement (Set of Four)

Set of 4 Tires to be Mounted and Balanced.

Description	Price	QTY	HRS	Subtotal
Labor: Tire Replacement			1.5	\$135.00
Labor: Additional Labor For Center Lock GT3RS Wheels			1	\$90.00
Part: Michelin 245/35R19 PS4S	\$281.50	2		\$563.00
Part: Michelin 325/30R19 PS4S	\$420.57	2		\$841.14
Fee: Shipping				\$115.31



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2094

Created: 10/29/2024 at 3:19PM
 Invoiced: 10/29/2024 at 4:24PM
 Payment Term: Net 10
 Payment Due: 11/08/2024
 Service Writer: Tom Lerich

Tire Replacement (Set of Four)	
Fee: Tire Disposal	\$35.00
Shop Supplies (5%): \$11.25	Total: \$1,790.70

Horn Button Repair				
Re-routed Airbag Wiring/Lubricated Airbag Surround With Silicone Grease				
Description	Price	QTY	HRS	Subtotal
Labor: Horn Button Repair/Re-routed Airbag Wiring/Lubricated Airbag Surround			0.8	\$72.00
Part: Silicone Grease	\$3.30	1		\$3.30
Shop Supplies (5%): \$3.60				Total: \$78.90

Removal Of Salbelt Harnesses		
Description	HRS	Subtotal
Labor: Removal Of Salbelt Harnesses	2	\$180.00
Shop Supplies (5%): \$9.00		Total: \$189.00

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

Labor	\$828.00
Parts	\$1,632.98
Subtotal	\$2,460.98
Shop Supplies	\$25.00
Fees	\$150.31
Tax	\$0.00
Grand Total	\$2,636.29
Paid to Date	(\$2,636.29)
REMAINING BALANCE	\$0.00

Payments	
11/19/2024	Check #2806 \$2,636.29
Total Payments	\$2,636.29