



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2228

Created: 02/25/2025 at 2:21PM
 Invoiced: 05/13/2025 at 12:14PM
 Payment Term: Net 10
 Payment Due: 05/23/2025
 Service Writer: Thomas Romanin

Switchcars Inc
 1521 Highland Road
 Twinsburg, OH 44087
 Office: (216) 453-0507
 info@switchcars.com

2002 BMW M3 (White)
 VIN: WBSBL934X2JR17357
 Mileage In: 65,346 mi
 Mileage Out: 65,346 mi

Recommendations

FL Wheel did not need wheel weights

R & R Connecting Rod Bearings				
Description	Price	QTY	HRS	Subtotal
Labor: R & R Connecting Rod Bearings			12	\$1,080.00
Part: Turner Motorsport Bearing Overhaul Kit - ACL Rod Bearing Set ARP Connecting Rod bolts Oil Pan Gasket	\$419.07	1		\$419.07
Part: Liqui-Moly 10W-60 Full Synthetic (1L)	\$9.68	7		\$67.76
Part: Hengst Oil Filter	\$10.35	1		\$10.35
Subcontract: 4 Wheel Alignment	\$145.00			\$145.00
	Shop Supplies (5%): \$25.00			Total: \$1,747.18

Vanos Exhaust Hub Update				
Description	Price	QTY	HRS	Subtotal
Labor: Vanos Exhaust Hub Update			8	\$720.00
Part: VAC Vanos Exhaust Hub Update Kit	\$1,035.09	1		\$1,035.09
	Shop Supplies (5%): \$25.00			Total: \$1,780.09

R & R Rear Subframe				
Description	Price	QTY	HRS	Subtotal
Labor: R & R Rear Subframe			8	\$720.00
Part: Turner Motorsport Rear Subframe Kit	\$114.39	1		\$114.39
Subcontract: Welding	\$250.00			\$250.00
	Shop Supplies (5%): \$25.00			Total: \$1,109.39

Replace Four Tires - Michelin Pilot 4S Tires				
Description	Price	QTY	HRS	Subtotal
Labor: Mount and Balance Four Tires			1.5	\$135.00
Part: FL Anti-Rattle Clip	\$8.40	1		\$8.40
Tire: 225/40R19 Michelin Pilot Sport 4S	\$256.07	2		\$512.14



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2228

Created: 02/25/2025 at 2:21PM
 Invoiced: 05/13/2025 at 12:14PM
 Payment Term: Net 10
 Payment Due: 05/23/2025
 Service Writer: Thomas Romanin

Replace Four Tires - Michelin Pilot 4S Tires			
Tire: 255/35R19 Michelin Pilot Sport 4S	\$252.04	2	\$504.08
Fee: Shipping			\$85.66
Fee: Tire Disposal			\$35.00
	Shop Supplies (5%): \$6.75		Total: \$1,287.03

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

Labor	\$2,655.00
Parts	\$1,655.06
Tires	\$1,016.22
Subcontracts	\$395.00
Subtotal	\$5,721.28
Shop Supplies	\$25.00
EPA	\$0.00
Fees	\$120.66
Tax	\$0.00
Grand Total	\$5,866.94
Paid to Date	(\$5,866.94)
REMAINING BALANCE	\$0.00

Payments		
6/5/2025	Check #2983	\$5,866.94
Total Payments		\$5,866.94

Authorizations		
In Person by Switchcars Inc 5/13/2025 at 12:10 PM EDT	+ Vanos Exhaust Hub Update + Replace Four Tires - Michelin Pilot 4S Tires + R & R Connecting Rod Bearings + R & R Rear Subframe	\$5,858.54



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2239

Created: 03/04/2025 at 12:48PM
 Invoiced: 05/16/2025 at 5:06PM
 Payment Term: On Receipt
 Payment Due: 05/16/2025
 Service Writer: Tom Lerich

2002 BMW M3 (White)
 VIN: WBSBL934X2JR17357
 Mileage In: 65,341 mi
 Mileage Out: 65,392 mi
 PSI: FL 32 FR 32 RL 34 RR 34

Recommendations

Change Oil In Around 1500-2000 Miles!!!! We use LiquiMoly 10W-60
 FL Wheel did not need wheel weights!!!
 Customer supplied driveshaft was not delivered or installed due to manufacture delays
 This relocated SMG pump system will self prime on occasion which makes a slight priming/ABS pump style noise
 All these prices quoted are accurate when in conjunction with the other services from Invoice 2228
 There may be additional service fabrication needed and charged on Customer Supplied Parts that do not properly fit!!

There is NO Parts Or Labor Warranty on any customer supplied parts

R & R Flywheel, Clutch And Driveshaft

Lightweight flywheel do "chatter" at certain RPM ranges due to their design. This his highly documented for all vehicles. We DO NOT recommend changing transmission fluid weights to muffle the chatter.

Description	Price	QTY	HRS	Subtotal
Labor: R & R Flywheel, Clutch And Driveshaft			12	\$1,620.00
Part: Customer Supplied Flywheel, Clutch And Driveshaft		1		\$0.00
Part: BMW Driveshaft Gasket/Enclosed In Vehicle	\$7.15	1		\$7.15
Shop Supplies (5%): \$25.00			Estimated Tax (6.75%): \$111.52	Total: \$1,763.67

R & R Brake Lines And Brake Flush

Description	Price	QTY	HRS	Subtotal
Labor: R & R Brake Lines/Flush Brake System			2.5	\$337.50
Part: TMS SS Brake Line Kit	\$281.74	1		\$281.74
Part: Castrol SRF Brake Fluid Included With TMS Kit		1		\$0.00
Shop Supplies (5%): \$16.88			Estimated Tax (6.75%): \$42.94	Total: \$679.06

Transmission Fluid Change

Description	Price	QTY	HRS	Subtotal
Labor: Transmission Fluid Change			0.8	\$108.00
Part: Redline D4 ATF	\$17.54	2		\$35.08
Shop Supplies (5%): \$5.40			Estimated Tax (6.75%): \$10.02	Total: \$158.50

Differential Fluid Change

Description	Price	QTY	HRS	Subtotal
-------------	-------	-----	-----	----------



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2239

Created: 03/04/2025 at 12:48PM
 Invoiced: 05/16/2025 at 5:06PM
 Payment Term: On Receipt
 Payment Due: 05/16/2025
 Service Writer: Tom Lerich

Differential Fluid Change				
Description	Price	QTY	HRS	Subtotal
Labor: Differential Fluid Change			0.8	\$108.00
Part: Redline 75W-140	\$22.05	2		\$44.10
Shop Supplies (5%): \$5.40			Estimated Tax (6.75%): \$10.63	Total: \$168.13

Magnetic Drain Plugs				
Description	Price	QTY	HRS	Subtotal
Part: Turner Titanium Engine Magnetic Drain Plugs	\$31.04	1		\$31.04
Part: Transmission Magnetic Drain Plug	\$19.54	1		\$19.54
Part: Differential Magnetic Drain Plugs	\$43.74	1		\$43.74
Shop Supplies (5%): \$0.00			Estimated Tax (6.75%): \$6.37	Total: \$100.69

Rear Main Seal And Pressure Valve				
Description	Price	QTY	HRS	Subtotal
Labor: R & R Rear Main			1	\$135.00
Labor: R & R Pressure Valve			0.8	\$108.00
Part: BMW Rear Main Seal	\$171.33	1		\$171.33
Part: Pressure Valve Replacement Kit	\$73.60	1		\$73.60
Shop Supplies (5%): \$12.15			Estimated Tax (6.75%): \$33.76	Total: \$533.84

Ignition Coils And Spark Plugs				
Description	Price	QTY	HRS	Subtotal
Labor: R & R Spark Plugs			0.6	\$81.00
Part: Dinan Ignition Coils	\$28.74	6		\$172.44
Part: NGK 7415 Spark Plugs	\$14.62	6		\$87.72
Shop Supplies (5%): \$4.05			Estimated Tax (6.75%): \$23.30	Total: \$368.51

Valve Adjustment				
Shims are \$3.00 and replaced as a "per-needed" basis. Maximum number of needed shims is 24/				
Description	Price	QTY	HRS	Subtotal
Labor: Valve Adjustment All Intake Valves Were Between .18-22mm All Exhaust Valve Were Between .28-32mm			1	\$135.00
Part: Valve Shims		1		\$0.00
Shop Supplies (5%): \$6.75			Estimated Tax (6.75%): \$9.57	Total: \$151.32

Install Performance Oil Cooler Installation				
Description	Price	QTY	HRS	Subtotal



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2239

Created: 03/04/2025 at 12:48PM
 Invoiced: 05/16/2025 at 5:06PM
 Payment Term: On Receipt
 Payment Due: 05/16/2025
 Service Writer: Tom Lerich

Install Performance Oil Cooler Installation				
Labor: Performance Oil Cooler Installation			3	\$405.00
Part: Customer Performance Oil Cooler Installation		1		\$0.00
Shop Supplies (5%): \$20.25			Estimated Tax (6.75%): \$28.70	Total: \$453.95

Install Performance Power Steering Reservoir				
Description	Price	QTY	HRS	Subtotal
Labor: Install Performance Power Steering Reservoir/Includes Power Steering System Flush			2.5	\$337.50
Part: BG Power Steering Flush System GREEN	\$85.06	1		\$85.06
Part: Customer Supplied Performance Power Steering Reservoir		1		\$0.00
Shop Supplies (5%): \$16.88			Estimated Tax (6.75%): \$29.66	Total: \$469.10

Install Underdrive Pulley Set				
Description	Price	QTY	HRS	Subtotal
Labor: Install UnderDrive Pulley Set			1	\$135.00
Part: Customer Supplied UnderDrive Pulley Set		1		\$0.00
Shop Supplies (5%): \$6.75			Estimated Tax (6.75%): \$9.57	Total: \$151.32

Coolant Flush				
Description	Price	QTY	HRS	Subtotal
Labor: Coolant Flush			1	\$150.00
Part: BMW Coolant/Antifreeze (1 Gallon) <i>Genuine BMW</i>	\$31.59	1.5		\$47.39
Part: Coolant Tank Bleeder Screw <i>BMW Coolant Bleeder Screw for E30, E36, E46, E34, E39, E38, E31, E53, E83, Z3, Z4, Z8</i>	\$6.43	1		\$6.43
Part: Redline WaterWetter Coolant Treatment	\$11.78	1		\$11.78
Shop Supplies (5%): \$7.50			Estimated Tax (6.75%): \$15.06	Total: \$238.16

Extra Parts And Service				
We recommend tack welding the exhaust tips after a couple thousand miles once the exhaust settles into position				
Description	Price	QTY	HRS	Subtotal
Labor: R & R Motor And Transmission Set			0.5	\$75.00
Labor: R & R Fuel Filter			0.4	\$60.00
Labor: Install Powerflex Polyurethane Rear Subframe				\$0.00
Labor: Lowering Spring Installation			3	\$450.00
Labor: Install Valvetronic Exhaust			0.67	\$100.00



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2239

Created: 03/04/2025 at 12:48PM
 Invoiced: 05/16/2025 at 5:06PM
 Payment Term: On Receipt
 Payment Due: 05/16/2025
 Service Writer: Tom Lerich

Extra Parts And Service			
Labor: R & R Coolant Hoses		0.6	\$90.00
Labor: R & R Differential Bushings		1	\$150.00
Labor: Trailing Arm Bushings		1	\$150.00
Labor: R & R Front control Arm Bushings		0.8	\$120.00
Labor: Installed Customer Supplied USB Jacks		0.6	\$90.00
Labor: Install Customer Supplied BMW Fire Extinguisher		0.8	\$120.00
Part: BG Products Engine Assurance Kit Oil Cleaner/Conditioner	\$26.53	1	\$26.53
Part: Rubber Mount Steering Line	\$4.59	1	\$4.59
Part: URO Brass Bleeder	\$9.99	1	\$9.99
Part: Turner Density Motor And Transmission Set	\$248.59	1	\$248.59
Part: Mahle Fuel Filter	\$53.39	1	\$53.39
Part: Powerflex Polyurethane Rear Subframe Rear Position Bushing Insert	\$86.24	1	\$86.24
Part: BMW Flywheel Bolts	\$5.29	8	\$42.32
Part: BMW Lock Fastener	\$3.41	1	\$3.41
Part: Exhaust Gaskets	\$23.28	2	\$46.56
Part: Eibach Pro-Kit Spring Kit	\$318.56	1	\$318.56
Part: Valvetronic Exhaust	\$1,484.19	1	\$1,484.19
Part: Exhaust Bracket	\$46.91	1	\$46.91
Part: 12V Power Socket EXHAUST	\$17.49	1	\$17.49
Part: BMW Coolant Hose Under Intake	\$53.58	1	\$53.58
Part: BMW Coolant Hose Under Intake	\$40.95	1	\$40.95
Part: Intake Boot Clamp	\$4.50	1	\$4.50
Part: ECS Differential Bushing Front	\$33.76	1	\$33.76
Part: ECS Differential Bushings Rear Position	\$77.47	1	\$77.47
Part: PowerFlex Rear Trailing Arm Bushings	\$101.19	1	\$101.19
Part: Customer Supplied Front control Arm Bushings		1	\$0.00
Part: Customer Supplied USB Jacks		1	\$0.00
Part: Customer Supplied BMW Fire Extinguisher		1	\$0.00
Shop Supplies (5%): \$25.00		Estimated Tax (6.75%): \$278.79	Total: \$4,409.01



CAE Motorsport, LLC
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 260-0742
 service@caemotorsport.com
 www.caemotorsport.net

Invoice #2239

Created: 03/04/2025 at 12:48PM
 Invoiced: 05/16/2025 at 5:06PM
 Payment Term: On Receipt
 Payment Due: 05/16/2025
 Service Writer: Tom Lerich

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

Labor	\$5,065.00
Parts	\$3,818.36
Subtotal	\$8,883.36
Shop Supplies	\$25.00
EPA	\$0.00
Tax	\$601.31
Grand Total	\$9,509.67
Paid to Date	(\$9,509.67)
REMAINING BALANCE	\$0.00

Payments		
3/11/2025	Credit card ending in	\$3,500.00
4/28/2025	Credit card ending in	\$3,500.00
5/19/2025	Credit card ending in	\$2,509.67
Total Payments		\$9,509.67

Authorizations		
In Person by 4/4/2025 at 1:08 PM EDT	+ R & R Flywheel, Clutch And Driveshaft + Magnetic Drain Plugs + Extra Parts And Service	\$9,509.67 +\$4,027.63
In Person by 4/4/2025 at 1:08 PM EDT	+ Magnetic Drain Plugs + Differential Fluid Change + Rear Main Seal And Pressure Valve + R & R Flywheel, Clutch And Driveshaft + Install Performance Oil Cooler Installation + Coolant Flush + Install Underdrive Pulley Set + Ignition Coils And Spark Plugs + Valve Adjustment + R & R Brake Lines And Brake Flush + Extra Needed Parts + Transmission Fluid Change + Install Performance Power Steering Reservoir	\$5,482.04

BEN'S WORKSHOP

117 East Oltorf Street
Austin, TX 78704
(512) 472-5555

MERCEDES-BENZ SERVICE & REPAIR SINCE 1979

Repair Order #0109783

Date : 5/28/2025 Page 1 of 1

Orig Est #: Center : 1

Customer		VEHICLE : 2002 BMW M3	
Address	D	LICENSE : PAPER	COLR : WHITE
City		V.I.N. : WBSBL934X2JR17357	
Phone 1	Ext :	Fleet #:	TRANS : MANUAL
Phone 2	Ext :	ENGINE : S54	Mod : E46
		MILEAGE : 67032	

Parts				Labor				
Quan	Part Number	Description	Price	Op	Tech	Description	Time	Charge
1.00	11 42 7 833 769	OIL FILTER S54	32.00	PM	001 04	CHANGE OIL AND FILTER. CHECK FLUID LEVELS & SET TIRE PRESSURES.		87.50
	Location:	R1B3C		MS	001 04	HAZ-MAT WASTE DISPOSAL		12.50
6.00	LM2024	10W-60 MOTOR OIL	109.56					
	Location:	R5EED						

WARRANTY ON REPAIRS IS 12 MONTHS OR 12,000 MILES WHICHEVER OCCURS FIRST.

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequences due to the unavailability of parts shipments beyond their control.

SPECIAL WARRANTY NOTE:

All repairs performed to antique vehicles (1999 and earlier) are billed on a time and materials basis and are warranted at the sole discretion of Ben's Workshop

Labor :	\$100.00
Parts :	\$141.56
Sublet :	\$0.00
Other Fees :	\$0.00
Supplies :	\$8.45
Subtotal :	\$250.01
Sales Tax :	\$12.38
Total :	\$262.39
Paid :	\$0.00
Due :	\$262.39

Signature X _____



**DESERT
B.M.W.**
BIMMER MOTOR WERKS

Desert Bimmer Motor Werks

781 S Arizona Ave
Chandler, AZ 85225
Phone: 480-895-7785

06/10/2025

Invoice #
7653

PAID

2002 BMW M3

Odometer In: 68144

Odometer Out: 68146

VIN: WBSBL934X2JR17357

Eng: 3.2L, In-Line6 (198CI)

Hat #795

Vehicle Time In: 6/9/2025 4:39:30PM

Vehicle Time Out: 6/10/2025 10:50:36AM

Description Of Services

CUSTOMER STATES TEMP GAUGE WAS GOING UP WHEN STOPPED IN TRAFFIC

Performed short test, connected battery charger. No faults stored in vehicle for overheat or anything that would cause overheat. Found coolant level sufficient and cooling fans operating normally. Test drove vehicle after oil service to get vehicle up to operating temperature and then let idle in parking lot for 15 minutes. Both coolant and oil temperature's stayed in middle position w/o deviating indicating normal operating temperatures when tested. No recommendation at this time

Labor: \$195.00 Parts: \$0.00 Sublet:\$0.00 Job Total: \$195.00

OIL SERVICE DUE

Perform Oil Service and Reset SIA Data

Description	Quantity	List	Sale	Extended
LiquiMoly 10W-60 Synthetic (1 Liter)	6.00	\$15.97	\$15.97	\$95.82
Oil Filter Kit	1.00		\$19.22	\$19.22
Air Filter	1.00	\$44.46	\$44.46	\$44.46

Labor: \$45.99 Parts: \$159.50 Sublet:\$0.00 Job Total: \$205.49

CUSTOMER STATES TPM LIGHT ON NEEDS REST CHECK AND ADVISE

Set tire pressures to spec and initialized TPM system





Desert Bimmer Motor Werks

781 S Arizona Ave
Chandler, AZ 85225
Phone: 480-895-7785

06/10/2025

Invoice #
7653

PAID

2002 BMW M3
Odometer In: 68144

Odometer Out: 68146
VIN: WBSBL934X2JR17357
Eng: 3.2L, In-Line6 (198CI)
Hat #795

Description Of Services

Continued From Previous Page

Recommendations

- 06/09/2025 Tires PSI-Frt: 33 /RR: 38
Tires Measurement-Frt: 8/32 /RR: 8/32
Brakes Measurement-Frt: 10mm/ RR: 9mm
Additional Notes:
- 11/12/2025 Perform Lube, Oil & Filter Exchange on 11/12/2025 or 73100 Miles.

Service Advisor: ,
Technician(s): Atencio, DJ

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is two years or 24,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. All warranty work is from the original service date of repair paid for by the customer and cannot exceed 2 years or 24,000 miles from that repair. Warranty coverage only applies to new or re-manufactured parts sold by our service center and does not include used parts or parts provided by the customer. Any repairs performed with used parts or parts provided by the customer will exclude any and all part and labor warranties. Any aftermarket parts and/or software installed on vehicle may void parts and labor warranty if deemed that it has interfered with the function of parts replaced

Labor Total:	\$240.99
Parts Total:	\$159.50
Shop Sup.:	\$0.00
HazMat:	\$10.00

Sub Total:	\$410.49
Tax Total:	\$12.44
Grand Total:	\$422.93
Balance Due:	\$0.00



SIGNATURE.....**Date** June 10, 2025 10:50 am

Payment(s)
6/10/2025 10:50:33AM \$422.93 Elec - Credit Card Auth: SALE:844280:196589264::2161517620:Y:: 2161517620-Amex-2010



Avus Autosport

312 Vine St.
Glendale, CA 91204
818-500-7663

Customer Copy

Invoice #24342

Estimated
Time Due

Friday, July 11, 2025
1:40:26 PM

Ordered on
Tuesday, July 08, 2025

Workorder # 24955

MAKE & MODEL		FLEET NO.	PHONE	REP	CSH	PO #	TERMS
2002 BMW M3				Sandro Parra	SP		Cash
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
69198 / 69203		WBSBL934X2JR17357					
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	TOTAL	Code
SL	CUSTOMER REQUESTS NEW BRAKE PADS AND ROTORS. DUE TO CURRENT BRAKES BEING WARPED ROTORS	2		215.00		\$430.00	KK-SP
	CUSTOMER REQUESTS M3 COMPETITION ROTORS BE INSTALLED, WITH HIGH PERFORMANCE PADS						
SB	SHIPPING	1		48.00		\$48.00	SP
OP	34-11-2-282 445 FRONT ROTOR	1	724.36			\$724.36	KK-SP
OP	34-11-2-282 446 FRONT ROTOR	1	724.36			\$724.36	KK-SP
OP	R4-S BRAKE PAD SET	1	260.90			\$260.90	KK-SP
OP	BRACKET SET	1	273.92			\$273.92	KK-SP
	Subtotal		1,983.54	478.00		\$2,461.54	
SL	CUSTOMER REQUESTS OIL CHANGE	0.5		215.00		\$107.50	KK-SP
OP	LIQUI MOLY RACE TECH GT1	6	17.59			\$105.54	KK-SP
11-42-7-833-769	Oil Filter	1	26.62			\$26.62	
	Subtotal		132.16	107.50		\$239.66	
SL	SECURE LEFT TAIL LIGHT BULB HOUSING	0		215.00		\$0.00	KK-SP
	Subtotal		.00	.00		\$0.00	
SL	INSTALL WHITE TURN SIDE MARKERS	0		215.00		\$0.00	KK-SP
OP	63-13-7-165-846 WHITE TURN SIGNAL SIDE MARKER	1	42.79			\$42.79	KK-SP
	Subtotal		42.79	.00		\$42.79	

Welcome, We appreciate your business.

PAID BY	Parts	\$2,158.49	Taxable	\$2,158.49
AMEX \$2,970.63	Labor	\$585.50	Non-Taxable	\$585.50
	Freight	\$0.00	Local Tax	\$226.64
	Other	\$0.00		
	Supplies	\$0.00		
	TOTAL		\$2,970.63	

Parts and Labor warranty is for two years or 24,000 miles, whichever comes first. This warranty does not apply to wear items such as brakes, clutches, belts, and wiper refills. This warranty applies to work completed and listed on this repair order only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials and labor. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. Avus Autosport will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. No refunds whatsoever, unless special arrangements have been arranged by Avus Autosport. Absolutely no returns or refunds on special orders or discontinued items. All returns items that are approved by Avus Autosport are subject to 30% restocking charge. Any deposits are subject to forfeit if in progress work is cancelled. I agree to pay \$200 per per day for indoor storage if my vehicle is not picked up within 24 hours of completion, unless authorized in writing by Avus Autosport.

Print Name _____ Signature _____ Date _____

Avus Autosport

312 Vine St.
Glendale, CA 91204
818-500-7663

Customer Copy

Invoice #24408

Estimated
Time Due

Tuesday, August 12, 2025
~~10:30:32 AM~~

Ordered on
Friday, August 08, 2025

Workorder # 25032

MAKE & MODEL		FLEET NO.	PHONE	REP	CSH	PO #	TERMS
2002 BMW M3				Sandro Parra	SP		Cash
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
	70441	WBSBL934X2JR17357					
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	TOTAL	Code
SL	CHECK FOR OIL LEAK, customer approved	2.5		215.00		\$537.50	HM-SP
OP	83-29-0-429-576	1	47.07			\$47.07	HM-SP
OP	32-41-2-282-353 POWER STEERING HOSE	1	280.97			\$280.97	HM-SP
OP	32-41-2-229-369 P/S RETURN HOSE	1	65.23			\$65.23	HM-SP
	Subtotal		393.27	537.50		\$930.77	
SL	CUSTOMER STATES HAZARD LIGHT SWITCH AND LOCK SWITCH DONT WORK	0		215.00		\$0.00	HM-SP
OP	61-31-8-368-920 SWITCH	1	58.90			\$58.90	HM-SP
	Subtotal		58.90	.00		\$58.90	
SL	CUSTOMER REQUESTS EXHAUST TIPS BE INSTALLED AND EXHAUST BE ADJUSTED	2		215.00		\$430.00	HM-SP
OP	3" EXHAUST TIP	4	29.99			\$119.96	HM-SP
	Subtotal		119.96	430.00		\$549.96	
SL	CUSTOMER REQUESTS LEFT BULB HOLDER BE REPLACED	0		215.00		\$0.00	HM-SP
OP	63-21-8-364 729 BULB CARRIER LEFT	1	49.81			\$49.81	HM-SP
	Subtotal		49.81	.00		\$49.81	

Welcome, We appreciate your business.

PAID BY	Parts	\$621.94	Taxable	\$621.94
AMEX \$1,654.74	Labor	\$967.50	Non-Taxable	\$967.50
	Freight	\$0.00	Local Tax	\$65.30
	Other	\$0.00		
	Supplies	\$0.00		
	TOTAL		\$1,654.74	

Parts and Labor warranty is for two years or 24,000 miles, whichever comes first. This warranty does not apply to wear items such as brakes, clutches, belts, and wiper refills. This warranty applies to work completed and listed on this repair order only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials and labor. You and your employees may operate vehicle for purposes of testing, inspection or delivery of my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. Avus Autosport will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. No refunds whatsoever, unless special arrangements have been arranged by Avus Autosport. Absolutely no returns or refunds on special orders or discontinued items. All returns items that are approved by Avus Autosport are subject to 30% restocking charge. Any deposits are subject to forfeit if in progress work is cancelled. I agree to pay \$200 per per day for indoor storage if my vehicle is not picked up within 24 hours of completion, unless authorized in writing by Avus Autosport.

Print Name _____ Signature _____ Date _____

Avus Autosport

312 Vine St.
Glendale, CA 91204
818-500-7663

Customer Copy

Invoice #24469

Estimated
Time Due

Friday, September 12, 2025
3:03:48 PM

Ordered on
Friday, August 29, 2025

Workorder # 25080

MAKE & MODEL	FLEET NO.	PHONE	REP	CSH	PO #	TERMS	
2002 BMW M3			Sandro Parra	SP		Cash	
LICENSE NO.	MILES IN/OUT	VIN	TORQUE	ENGINE SIZE	TRANSMISSION	COLOR	PRD DATE
71836		WBSBL934X2JR17357					
CATALOG	DESCRIPTION	QTY	PARTS	LABOR	DISC	TOTAL	Code
SL	CUSTOMER STATES POWER STEERING FLUID CAN BE SEEN ON UNDERTRAY TECH RECENTLY REPLACED SEAL RINGS FOR AFTERMARKET RES, ALONG WITH THE TWO LINES COMING FROM THE RES TECH REPLACED O RING FOR FLUID TANK MID SECTION, USED THREAD SEALANT ON FLANGES	1		215.00		\$215.00	HM-SP
Subtotal				.00	215.00	\$215.00	
SL	CUSTOMER REQUESTS OIL CHANGE	0.5		215.00		\$107.50	HM-SP
OP	10W-60 LIQUIMOLY	6	17.59			\$105.54	HM-SP
11-42-7-833-769	Oil Filter	1	26.62			\$26.62	
Subtotal			132.16	107.50		\$239.66	

Welcome, We appreciate your business.

PAID BY	Parts	\$132.16	Taxable	\$132.16
AMEX \$468.54	Labor	\$322.50	Non-Taxable	\$322.50
	Freight	\$0.00	Local Tax	\$13.88
	Other	\$0.00		
	Supplies	\$0.00		
	TOTAL			\$468.54

Parts and Labor warranty is for two years or 24,000 miles, whichever comes first. This warranty does not apply to wear items such as brakes, clutches, belts, and wiper refills. This warranty applies to work completed and listed on this repair order only. Vehicle must be returned to our shop at customer's expense, to honor warranty. I hereby authorize the repair work to be done along with the necessary materials and labor. You and your employees may operate vehicle for purposes of testing, inspection or delivery at my risk. An express Mechanic's lien is acknowledged on vehicle to secure the amount of repairs thereto. Avus Autosport will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. No refunds whatsoever, unless special arrangements have been arranged by Avus Autosport. Absolutely no returns or refunds on special orders or discontinued items. All returns items that are approved by Avus Autosport are subject to 30% restocking charge. Any deposits are subject to forfeit if in progress work is cancelled. I agree to pay \$700 per per day for indoor storage if my vehicle is not picked up within 24 hours of completion, unless authorized in writing by Avus Autosport.

Print Name _____ Signature _____ Date _____