



GT PEACE AUTOMOTIVE

4003 WESTFAX DR STE G
 Chantilly, VA. 20151
 Phone: (703)-956-6499 | Fax: (703)-956-6501
 www.gtpeaceauto.com | gtpeaceauto@gmail.com
 YOUR COMPLETE AUTOMOTIVE REPAIR AND SERVICE SHOP!

Invoice # **038535**
 Original Est # 38200

Invoice

Paid Balance Due: **\$0.00**

2011 BMW - M3

4L, V8 (0CI) VIN(C)

VIN: WBSKG9C50 **BE368676**

Odometer: In 64,146 Out 64,170 Color: WHITE

Work Complete: 08/20/2025

Service Advisor: FREDDY COPPI...

Customer ID: 23338

Printed Date: 12/29/2025

Type	Description	Qty	Sale	Total
Job Title				\$0.00

Note -BE ROD BEARINGS AND BOLTS AND ENGINE MOUNTS (SOP ON SHELF)
 -STIFFENING PLATE(?)
 -EXHAUST GROUND CABLES(?)
 -HOOD STRUTS
 *DROP
 (FC)

Parts: \$0.00 Labor: \$0.00 Tax: \$0.00 Total: \$0.00

S65 ROD BEARINGS \$3,766.73

Labor REPLACE ENGINE CONNECTING ROD BEARINGS AND ENGINE MOUNTS. TECH INSTALLED NEW BE CONNECTING ROD BEARINGS, ARP CONNECTING ROD BOLTS, REPLACED THE ENGINE OIL PAN GASKET WITH NEW OIL AND FILTER. INSTALLED NEW ENGINE MOUNTS. \$1,897.50

Part BE Performance Connecting Rod Bearing Set Size: STOCK 1.00 \$599.99 \$599.99

Part BE Performance S65 Connecting Rod Bolt Set Size: STOCK 1.00 \$299.99 \$299.99

Part Oil Pan Gasket 1.00 \$72.73 \$72.73

Part OIL FILTER OE 1.00 \$31.01 \$31.01

Part MOTUL FULL SYNTHETIC 10W-60 Size: 5L 2.00 \$57.76 \$115.52

Part Engine Mount 2.00 \$80.00 \$160.00

Part A/C Belt Tensioner 1.00 \$165.00 \$165.00

Labor REPLACE FRONT LOWER CONTROL THRUST ARMS WHILE SUBFRAME IS DOWN. Tech replaced both front lower control thrust arm assemblies. \$0.00

Part Control Arm Strut-Front Left Lower 1.00 \$156.78 \$156.78

Part Control Arm Strut-Front Right Lower 1.00 \$162.40 \$162.40

Parts: \$1,763.42 Labor: \$1,897.50 Tax: \$105.81 Total: \$3,766.73

C/S RRT RECOMMENDED REPLACING THE STIFFENING PLATE(?) \$309.88

Labor C/S RRT RECOMMENDED REPLACING THE STIFFENING PLATE(?) AND EXHAUST GROUND CABLES(?) Tech verified the stiffening reinforcement plate got hit and is rubbing up against the oil pan. Tech replaced the stiffening plate and both exhaust ground cable straps. \$0.00

Part Stiffening Reinforcement Plate 1.00 \$171.60 \$171.60

Part Ground Cable 2.00 \$60.37 \$120.74

Parts: \$292.34 Labor: \$0.00 Tax: \$17.54 Total: \$309.88

REPLACE HOOD STRUTS \$138.72

Labor REPLACE HOOD STRUTS Tech replaced both hood struts. \$82.50

Part Hood Strut 2.00 \$26.52 \$53.04

Parts: \$53.04 Labor: \$82.50 Tax: \$3.18 Total: \$138.72

Type	Description	Qty	Sale	Total
PERFORM FRONT END ALIGNMENT AFTER REPAIRS				\$0.00
Labor	PERFORM FRONT END ALIGNMENT AFTER REPAIRS Tech performed front end wheel alignment.			\$0.00
Parts: \$0.00	Labor: \$0.00	Tax: \$0.00	Total: \$0.00	

Recommendations

- Perform Lube, Oil & Filter Exchange on 3/2/2026 or 69500 Miles.

All repairs hold a 24 month, 24,000 mile warranty ***

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. ***-ALL REPAIRS MADE AT GT PEACE AUTOMOTIVE WILL HOLD A 24 MONTH, 24,000 MILE WARRANTY (WHICH EVER COMES FIRST) WITH PARTS PROVIDED BY GT PEACE AUTOMOTIVE. AFTERMARKET PERFORMANCE PARTS/ RACING PARTS DO NOT HOLD ANY WARRANTY ON PARTS OR LABOR OF ANY KIND. ANY CUSTOMER PROVIDED PARTS WILL NOT RECEIVE ANY STATED WARRANTY.*** Warranty work will need to be performed in our shop & cannot exceed the original cost of repair.

Labor	\$1,980.00
Parts	\$2,108.80
Hazardous Materia	\$38.00
Shop Supplies	\$48.00
Subtotal	\$4,174.80
Taxes	\$129.41
Order Total:	\$4,304.21

Payment

Visa Paid \$4304.21 on 8/20/2025

Signature _____ Date _____ Time _____