

Switchcars
 1521 Highland Road
 Twinsburg, OH 44087
 (216) 453-0507
 info@switchcars.com
 www.switchcars.com

Invoice #1098

Created: 5/2/2022 11:15 AM EDT
 Invoiced: 7/19/2022 11:11 AM EDT
 Payment Term: On Receipt
 Service Writer: Thomas Romanin

Switchcars Inc
 1521 Highland Road
 Twinsburg, OH 44087
 Info@switchcars.com

1994 MERCEDES-BENZ SL-Class SL600
 VIN: WDBFA76E6RF087222
 Mileage In: 42,625
 Mileage Out: 42,625

Recommendations

oil leak
 front speakers buzzing

Transmission pan and gasket

Replace the transmission pan and gasket that are leaking. Fill and set transmission fluid level.

	Description	Price	QTY	HRS	Subtotal
1	R&R Transmission pan			2	\$130.00
2	Transmission Pan	\$68.85	1		\$68.85
3	Transmission Pan Gasket	\$5.54	1		\$5.54
4	Transmission fluid	\$8.25	6		\$49.50
				Shop Supplies (5%): \$6.50	Total: \$260.39

Oil Drain plug leak.

Swap seal on oil drain plug and reset oil level as needed.

	Description	Price	QTY	HRS	Subtotal
1	Oil Plug Seal Replacement			0.3	\$19.50
2	5w40 Oil	\$8.99	1		\$8.99
				Shop Supplies (5%): \$0.98	Total: \$29.47

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

Parts	\$132.88
Labor	\$149.50
Subtotal	\$282.38
Shop Supplies	\$7.48
Tax	\$0.00
Grand Total	\$289.86
Paid To Date	(\$0.00)

REMAINING BALANCE \$289.86

Authorizations

In Person by Switchcars Inc 7/19/2022 at 11:10 AM EDT	+ Transmission pan and gasket + Oil Drain plug leak.	\$289.86
-----------------------------------------------------------------	---------------------------------------------------------	-----------------