

CAE Motorsport 1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com Invoice #2203

Created: 2/3/2025 12:51 PM EST Invoiced: 2/18/2025 01:02 PM EST Payment Term: Net 10 Payment Due: 02/28/2025

Payment Due: 02/28/2025 Service Writer: David Rimback

Switchcars Inc

1521 Highland Road Twinsburg, OH 44087 Mobile: (216) 453-0507 info@switchcars.com

2006 MERCEDES-BENZ E-Class E 55 AMG (Black)

VIN: WDBUF76J16A922013

Mileage In: 94,527 Mileage Out: 94,632

Recommendations

KeyLess Go does not work

Veh	icle Inventory Inspection				
	Description	Price	QTY	HRS	Subtotal
1	Vehicle Inventory Inspection			1	\$90.00
2	LOF			0.5	\$45.00
3	BG Assurance Kit	\$23.87	1		\$23.87
4	Mann Oil Filter	\$14.75	1		\$14.75
5	Mobil One 5W-40 Full SYN	\$7.70	9		\$69.30
		Shop Supplies (5%)	: \$6.75	Tota	l: \$249.67

Bra	ke Fluid Flush				
	Description	Price	QTY	HRS	Subtotal
1	Brake Fluid Flush			1.5	\$135.00
2	Pentosin Super DOT4 Brake Fluid (1L)	\$15.41	1		\$15.41
	Shop Supplies (5%): \$6.75		: \$6.75	Tota	l: \$157.16

Rep	Repair Coolant Hose/Pressure Test System					
	Description	Price	QTY	HRS	Subtotal	
1	Repair Coolant Hose/Pressure Test System			2	\$180.00	
2	Hose Connector	\$9.87	1		\$9.87	
3	5/8 Hose	\$15.39	1		\$15.39	
4	Hose Clamps	\$3.30	3		\$9.90	
5	BMW Coolant	\$27.45	0.5		\$13.73	
		Shop Supplies (5%): \$9.00		Tota	l: \$237.89	



CAE Motorsport 1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com Invoice #2203

Created: 2/3/2025 12:51 PM EST Invoiced: 2/18/2025 01:02 PM EST

Payment Term: Net 10 Payment Due: 02/28/2025 Service Writer: David Rimback

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _	
-------------	--

Parts Labor Subtotal Shop Supplies Tax Grand Total	\$450.00 \$622.22 \$22.50 \$0.00
Paid To Date	* -
REMAINING BALANCE	\$0.00

Payments		
3/4/2025	Check #2898	\$644.72

Authorizations		
In Person by Switchcars Inc 2/13/2025 at 4:55 PM EST	+ Repair Coolant Hose/Pressure Test System	\$644.72 +\$237.89
In Person by Switchcars Inc 2/13/2025 at 4:55 PM EST	+ Vehicle Inventory Inspection + Brake Fluid Flush	\$406.83



Inspected: 02/18/2025



CAE Motorsport 1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com

Switchcars Inc

1521 Highland Road Twinsburg, OH 44087 Mobile: (216) 453-0507 info@switchcars.com 2006 MERCEDES-BENZ E-Class E 55 AMG (Black)

VIN: WDBUF76J16A922013

Mileage In: 94,527 Mileage Out: 94,632

Inventory Inspection

	Item	Green	Yellow	Red	N/A
1	Read Out Diagnostic Codes		✓		
	Note/Recommendation: Drive vehicle for 100 miles then scan vehicle for	r codes			
2	Engine Oil	~			
	Note/Recommendation: Fresh oil change as of 2/18/25 and 94,632 mile	s			
3	Brakes/Brake Pad Thickness 3mm Minimum	✓			
	Note/Recommendation: F 10mm R 8mm				
4	Brake Fluid Humidity Test/3% Maximum	✓			
	Note/Recommendation: Brake flush as of 2/18/25 and 94,632 miles				
5	Tires Tread Depth/Date Stamp	✓			
	Note/Recommendation: F 6/32nds, 4820, 1121 R 5/32nds, 4122				
6	Spare Tire Condition And Air Pressure	✓			
	Note/Recommendation:				
7	Wheel Lock Present? Check For Compatibility				~
	Note/Recommendation:				
8	Convertible Top/Targa Top/Pano/Sunroof Operation/Sunshades	~			
	Note/Recommendation:				
9	Steering/Suspension/Wheel Bearings	~			
	Note/Recommendation:				



1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com

10	Transmission Fluid Level (if applicable)/Fluid Leaks/Drive Shaft Flex Joint(s) Guibo(s)	~		
	Note/Recommendation:			
11	Drivetrain Fluid Leaks-Front And Rear Differentials/Transfer Case/CV Boot Condition	~		
	Note/Recommendation:			
12	Battery/Inspect For Battery Vent Tube Where Applicable/Inspect And Clean Water Drains Near Battery Where Applicable	~		
	Note/Recommendation:			
13	Exhaust/Muffler/Clamps		~	
	Note/Recommendation:			
14	Engine Belts	~		
	Note/Recommendation:			
15	Coolant Level/Coolant Hoses	~		
	Note/Recommendation:			
16	Power Steering Fluid Condition And Level/Power Steering Hoses	✓		
	Note/Recommendation:			
17	Electric Power Steering Condition			~
	Note/Recommendation:			
18	Power/Manual Seat Operations/Check Heating And Cooling Where Applicable			~
	Note/Recommendation:			
19	Power Side Mirror Movement Functions/Heating/Folding	~		
	Note/Recommendation:			
20	Gas Cap Seal	✓		
	Note/Recommendation:			
21	Air Filter	✓		
	Note/Recommendation:			



CAE Motorsport 1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com

22	Cabin Filter	✓		
	Note/Recommendation:			
23	Climate Control (A/C included)	✓		
	Note/Recommendation:			
24	Radio Reception/Volume Check	~		
	Note/Recommendation:			
25	Steering Wheel Button Function	~		
	Note/Recommendation:			
26	Lights (head, brake, turn)	~		
	Note/Recommendation:			
27	Interior Lighting	~		
	Note/Recommendation:			
28	Wipers	~		
	Note/Recommendation:			
29	Locks/Keys	~		
	Note/Recommendation:			
30	Horn	~		
	Note/Recommendation:			
31	Headliner Condition		~	
	Note/Recommendation: Slight De-laminating			
32	Clean Front And/Or Rear Air Ducts Of Debris			✓
	Note/Recommendation:			
33	Porsche Flat 6 Engines. Most 911/Cayman/Boxster 1999-2010. Are The Ignition Coils Updated?			✓
	Note/Recommendation:			
34	Porsche Battery Cavity Water Drains			✓





1521 Highland Road Twinsburg, OH 44087 (216) 260-0742 service@caemotorsport.com CAEmotorsport.com

Note/Recommendation:				
Totals	25	3	0	6