



CAE Motorsport, LLC
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
www.caemotorsport.net

Switchcars Inc
1521 Highland Road
Twinsburg, OH 44087
Office: (216) 453-0507
info@switchcars.com

Invoice #2701

Created: 11/26/2025 at 12:07PM

Invoiced: 12/10/2025 at 9:35AM

Payment Term: Net 10

Payment Due: 12/20/2025

Service Writer: Daniel Niedzwiecki

2013 Porsche Boxster Base (Blue)

VIN: WP0CA2A84DS114720

Mileage In: 22,272 mi

Mileage Out: 22,272 mi

| Inventory Vehicle Inspection and Oil Service | | | | |
|---|---------|----------------------------|-----|-----------------|
| Description | Price | QTY | HRS | Subtotal |
| 1 Multi-Point Inventory Inspection and Oil Service | | | 1.6 | \$144.00 |
| 2 5W-40 Euro Full Synth (1QT) Mobil1 | \$9.45 | | 7.5 | \$70.88 |
| 3 Oil Filter Mahle OX-366D <i>Boxster/Cayman 2009-2021</i> | \$23.19 | | 1 | \$23.19 |
| | | Shop Supplies (5%): \$7.20 | | Total: \$245.27 |

| Tire Replacement (Set of 2) | | | | |
|--|----------------------------|-----|-----|-----------------|
| Set of 4 Tires to be Mounted and Balanced. | | | | |
| Description | Price | QTY | HRS | Subtotal |
| 1 Rear Tire Replacement | | | 1.5 | \$135.00 |
| 2 265/40-19 Pirelli P Zero All Season RFT | \$227.72 | | 2 | \$455.44 |
| 3 Tire Disposal | | | | \$35.00 |
| | Shop Supplies (5%): \$6.75 | | | Total: \$632.19 |

| New Battery Installation | | | | |
|----------------------------|----------|-----|-----|-----------------|
| Description | Price | QTY | HRS | Subtotal |
| 1 R&R Battery | | | 0.5 | \$45.00 |
| 2 Battery | \$165.68 | | 1 | \$165.68 |
| Shop Supplies (5%): \$2.25 | | | | Total: \$212.93 |

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about any work performed.

Signature _____

| | |
|--------------------------|-------------------|
| Labor | \$324.00 |
| Parts | \$715.19 |
| Subtotal | \$1,039.19 |
| Shop Supplies | \$16.20 |
| EPA | \$0.00 |
| Fees | \$35.00 |
| Tax | \$0.00 |
| Grand Total | \$1,090.39 |
| Paid to Date | (\$0.00) |

REMAINING BALANCE **\$1,090.39**



CAE Motorsport, LLC
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
www.caemotorsport.net

Invoice #2701

Created: 11/26/2025 at 12:07PM

Invoiced: 12/10/2025 at 9:35AM

Payment Term: Net 10

Payment Due: 12/20/2025

Service Writer: Daniel Niedzwiecki

Authorizations

| | | |
|---|--|------------|
| In Person by Switchcars Inc 12/10/2025 at 9:34 AM EST | + Tire Replacement (Set of 2) + New Battery Installation + Inventory Vehicle Inspection and Oil Service | \$1,090.39 |
|---|--|------------|

Switchcars Inc
 1521 Highland Road
 Twinsburg, OH 44087
 Office: (216) 453-0507
 info@switchcars.com

2013 Porsche Boxster Base (Blue)
 VIN: WP0CA2A84DS114720
 Engine Size: 2.7L H6 (A122) GAS FI
 Transmission: AutomaticDualClutch
 Mileage In: 22,272 mi
 Mileage Out: 22,272 mi

Inventory Inspection

Inspected: 12/9/2025

| Item | Green | Yellow | Red | N/A |
|--|-------|--------|-----|-----|
| 1 Read Out Diagnostic Codes | ✓ | | | |
| Note/Recommendation: | | | | |
| 2 Engine Oil | ✓ | | | |
| Note/Recommendation: <i>Changed Oil and Filter. 12-9-2026</i> | | | | |
| 3 Brakes/Brake Pad Thickness 3mm Minimum | ✓ | | | |
| Note/Recommendation: <i>Front and Rear Brakes @ 8mm.</i> | | | | |
| 4 Brake Fluid Humidity Test/3% Maximum | ✓ | | | |
| Note/Recommendation: <i>Humidity @ 0%</i> | | | | |
| 5 Tires Tread Depth/Date Stamp | ✓ | | | |
| Note/Recommendation: <i>Front Left: 8/32" (1322) Front Right: 8/32" (4722) Rear Right: 9/32" (0823) - NEW Rear Left: 9/32" (0823) - NEW</i> | | | | |
| 6 Spare Tire Condition And Air Pressure | ✓ | | | |
| Note/Recommendation: | | | | |
| 7 Wheel Lock Present? Check For Compatibility | | | | ✓ |
| Note/Recommendation: | | | | |
| 8 Convertible Top/Targa Top/Pano/Sunroof Operation/Sunshades | ✓ | | | |
| Note/Recommendation: | | | | |
| 9 Steering/Suspension/Wheel Bearings | ✓ | | | |
| Note/Recommendation: | | | | |



CAE Motorsport, LLC
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
www.caemotorsport.net

Inspection #2701

Created: 11/26/2025

Invoiced: 12/10/2025

| Item | Green | Yellow | Red | N/A |
|--|-------|--------|-----|-----|
| 10 Transmission Fluid Level (if applicable)/Fluid Leaks/Drive Shaft Flex Joint(s) Guibo(s) | ✓ | | | |
| Note/Recommendation: | | | | |
| 11 Drivetrain Fluid Leaks-Front And Rear Differentials/Transfer Case/CV Boot Condition | ✓ | | | |
| Note/Recommendation: | | | | |
| 12 Battery/Inspect For Battery Vent Tube Where Applicable/Inspect And Clean Water Drains Near Battery Where Applicable | ✓ | | | |
| Note/Recommendation: | | | | |
| 13 Exhaust/Muffler/Clamps | ✓ | | | |
| Note/Recommendation: Aftermarket Borla Exhaust Equipped | | | | |
| 14 Engine Belts | ✓ | | | |
| Note/Recommendation: | | | | |
| 15 Coolant Level/Coolant Hoses | ✓ | | | |
| Note/Recommendation: | | | | |
| 16 Power Steering Fluid Condition And Level/Power Steering Hoses | ✓ | | | |
| Note/Recommendation: | | | | |
| 17 Electric Power Steering Condition | | | | ✓ |
| Note/Recommendation: | | | | |
| 18 Power/Manual Seat Operations/Check Heating And Cooling Where Applicable | ✓ | | | |
| Note/Recommendation: | | | | |
| 19 Power Side Mirror Movement Functions/Heating/Folding | ✓ | | | |
| Note/Recommendation: | | | | |
| 20 Gas Cap Seal | ✓ | | | |
| Note/Recommendation: | | | | |
| 21 Air Filter | ✓ | | | |

| Item | Green | Yellow | Red | N/A |
|---|-------|--------|-----|-----|
| Note/Recommendation: | | | | |
| 22 Cabin Filter | ✓ | | | |
| Note/Recommendation: | | | | |
| 23 Climate Control (A/C included) | ✓ | | | |
| Note/Recommendation: | | | | |
| 24 Radio Reception/Volume Check | ✓ | | | |
| Note/Recommendation: | | | | |
| 25 Steering Wheel Button Function | ✓ | | | |
| Note/Recommendation: | | | | |
| 26 Lights (head, brake, turn) | ✓ | | | |
| Note/Recommendation: | | | | |
| 27 Interior Lighting | ✓ | | | |
| Note/Recommendation: | | | | |
| 28 Wipers | ✓ | | | |
| Note/Recommendation: | | | | |
| 29 Locks/Keys | ✓ | | | |
| Note/Recommendation: | | | | |
| 30 Horn | ✓ | | | |
| Note/Recommendation: | | | | |
| 31 Headliner Condition | ✓ | | | |
| Note/Recommendation: | | | | |
| 32 Clean Front And/Or Rear Air Ducts Of Debris | ✓ | | | |
| Note/Recommendation: | | | | |
| 33 Porsche Flat 6 Engines. Most 911/Cayman/Boxster 1999-2010. Are The Ignition Coils Updated? | | | | ✓ |



CAE Motorsport, LLC
1521 Highland Road
Twinsburg, OH 44087
(216) 260-0742
service@caemotorsport.com
www.caemotorsport.net

Inspection #2701

Created: 11/26/2025

Invoiced: 12/10/2025

| Item | Green | Yellow | Red | N/A |
|--|-------|--------|-----|-----|
| Note/Recommendation: | | | | |
| 34 Porsche Battery Cavity Water Drains | ✓ | | | |
| Note/Recommendation: | | | | |
| 35 Underside Photos | ✓ | | | |
| Note/Recommendation: | | | | |
| Totals | 32 | 0 | 0 | 3 |